LC AUTOMOTIVE

Block 25 KAKI BUKIT ROAD 4 #05-26 SYNERG @KB (S)417800
Tel : (65) 65250431 HP: 92712214
Email :chris_chanbebe@hotmail.com

12th OCT 2020

TP 1st Cap.
Khanchnen. MPOS3REH1045403T3

25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

Accident date: 12nd OCT 2020
Estimated repair cost for vehicle no: SKX7999R TOYOTA COROLLA ALTIS 1.6

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet		$1,050.00 X
2	1	Front bonnet lock		$215.00 X
3	1	Front bonnet inner rubber		$155.00 X
4	6	Front bonnet inner rubber clips	$12.90	$77.40 X.
5	1	headlamp top chrome -LH cut		$188.00 ✓
6	1	Front headlamp -LH Cracked		$1,250.00 ✓
7	1	Front grille		$315.00 X
8	1	grille clips		$50.00 X
9	1	Front grille emble logo		$65.00 X
10	1	Front bumper Distorted		~~$820.00~~ 458.
11	2	Front Bumper Side Bracket LH Damaged	$123.20	$246.40 45
12	8	Front bumper clips NIL	$12.90	$103.20 30
13	1	Front bumper number plate Not avl		$50.00 X
14	1	Front bumper inner sponge Cracked		$182.00 ✓
15	2	front bumper side bracket Repainted	$135.00	$270.00 X
16	2	front bumper side retainer Repainted	$165.20	$330.40 X.
17	1	Front bumper fog lamp cover-LH cut		$155.00 ✓
18	1	Front fog lamp -LH Cracked		$254.00 ✓
19	1	Front air-con cleaner -top Defamed		$258.00 ✓
20	1	front air-con cleaner -lower Deformed		$265.00 ✓
21	1	Front fender -LH Dented		$725.00 ✓
22	1	Front fender mud shield -LH Torn		$153.90 ✓
23	1	Front fender inner cowling torn		$184.00 ✓
24	8	Front fender cowling clips NIL	$12.90	~~$103.20~~ 30
25	1	Front tyre-LH Not avl		$300.00 X
26	1	Front sport rim-LH cut		$400.00 ✓
27	1	Front shock absorber Bent		$325.00 ✓
28	1	Front knuckle arm-LH Damaged		$265.00 ✓
29	1	Front lower arm-LH Bent		$285.00 ✓
30	1	Front wheel bearing-lh Damaged		$188.00 ✓
			Subtotal :-	$9,228.50

5487
4115.25

Labour charges		
To remove & refit cushion	$120.00	X
To remove & refit front undercarriage	~~$280.00~~	200
To check wheel alignment computer	~~$150.00~~	80
To check wiring	~~$80.00~~	30
To remove & re-fix front air cleaner & top up gas	$150.00	X
	1410	
Tuff kote	$120.00	X
Panel beating	~~$1,000.00~~	500
Spray painting	~~$1,000.00~~	600
Subtotal :-	$2,900.00	
Total:-	$12,128.50	

total: 525.25

4/5: 4.4K

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPUTERISED 4 WHEEL ALIGNMENT
HUNTER DSP700

VIN: SKX 7999 R
Date 12.10.20 12:51

SKX 7999 R

TOYOTA ALTIS 2014-

Front : Left

Actual	Before	Specified Range
-1°30'	-1°30'	-0°59' 0°31'
3°08'	3°08'	5°08' 6°38'
-0°19'	-0°19'	0°00' 0°11'
21°11'	21°11'	
19°41'	19°41'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°14'	-0°14'	-0°59' 0°31'
3°35'	3°35'	5°08' 6°38'
-0°16'	-0°16'	0°00' 0°11'
8°23'	8°23'	
8°09'	8°09'	

Front

	Actual	Before	Specified Range
Cross Camber	-1°15'	-1°15'	-0°45' 0°45'
Cross Caster	-0°27'	-0°27'	-0°45' 0°45'
Cross SAI	12°47'	12°47'	
Total Toe	-0°35'	-0°35'	0°00' 0°22'
Cross Turn Diff.			

Rear : Left

Actual	Before	Specified Range
-1°40'	-1°40'	-1°58' -0°58'
0°10'	0°09'	-0°01' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°20'	-1°20'	-1°58' -0°58'
0°01'	0°00'	-0°01' 0°16'

Rear

	Actual	Before	Specified Range
Cross Camber	-0°21'	-0°21'	-0°30' 0°30'
Total Toe	0°11'	0°09'	-0°01' 0°31'
Thrust Angle	0°04'	0°05'	