

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24060001/EMA3Q2
Date: 06/02/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800075916
Claimant Vehicle No : SLH9999A **Insured Vehicle No :** SMC1230B
Date of Loss: 07/06/2024 Nature of Claim: TP Claim No: 0945243717SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH9999A**
Make & Model: AUDI Q5, 2.0 TFSI QU S TRONIC (A) Engine No: DGK006528
Reg. Date: 20/08/2021 (Man. Year: 2021) Chassis No: WAUZZZF1M2099157
Colour: Black Odometer: 21763 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R20 Rear Tyre Size: 255/45 R20
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,997.00	5,787.20	5,209.80	47.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,752.00	2,652.00	2,100.00	44.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,749.00	8,439.20	7,309.80	46.41
+ GST 9.00/9.00% (S\$)	1,417.41	759.53	657.88	46.41
Nett Amount (S\$)	17,166.41	9,198.73	7,967.68	46.41
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		9,500.91		

INSPECTION

Date of Assignment: 12/06/2024
Date Inspected: 12/06/2024 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	3,837.00 FS	*3,069.60 FS
2	2		*REAR BUMPER TRIM LH/RH	Not Necessary	286.00 FS	*- FS
3	1		*REAR BUMPER BLACK SPOILER	Cut	406.00 FS	*324.40 FS
4	1		*REAR DIFFUSER	Cut	423.00 FS	*338.00 FS
5	1		*REAR TRIM LH/RH	N/S Cut	614.00 FS	*245.20 FS
6	1		*REAR TRIM CENTRE	Not Necessary	209.00 FS	*- FS
7	1		*REAR TAILLIGHT LH /RH	N/S Broken	1,750.00 FS	*699.60 FS
8	1		*REAR SENSOR	Not Necessary	286.00 FS	*- FS
9	4		*REAR SENSOR SEAL	Not Necessary	11.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,195.00 FS	*- FS
11	1		*REAR BUMPER FOAM	Not Necessary	79.00 FS	*- FS
12	1		*REAR BUMPER HOLDING STRAP	Not Necessary	213.00 FS	*- FS
13	2		*REAR WHEEL COVER REAR LH/RH	Necessary	1,388.00 FS	*1,110.40 FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
					Total Parts (\$\$)	10,997.00 5,787.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER REORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER UPPER ,REAR BUMPER MID AND BOTH REAR WHEEL ARCH TRIMS	New	2,500.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			4,752.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >