

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP24040088

Date: 01 JUL 2024

**MAC Auto Pte Ltd**  
**C/o Eng Soon Painting SVC**  
**Blk 4 Yew Tee Ind Est 393 - J**  
**Woodlands Road**  
**Singapore 677969**

## THIRD PARTY SURVEY ACCIDENT OCCURED ON 20 APR 2024

Workshop Name and Address

Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

As per your instruction dated 29 MAY 2024  
We have carried out a physical inspection on the said  
We enclosed herewith our report and findings as follows:

with regard to the above matter.  
GBD4523L

### 1. VEHICLE PARTICULARS

Registration No : GBD4523L  
Model : TOYOTA DYNA 150  
Year / Capacity : May 2015 / 2986 cc  
Chassis No : JTFAT35Y30K203777

Engine No : 1KD2489916  
Mileage : 205 426km  
Colour : Silver

### 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Michelin	9.00 mm	Normal
REAR O/S :	155 / R 12	Linam	9.00 mm	Normal
FRONT N/S :	195/50/R15	Michelin	9.00 mm	Normal
REAR N/S :	155 / R 12	Linam	9.00 mm	Normal

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **front & side** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete
5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

## Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBD4523L

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front headlamp assy	Cracked	\$ 520.00	\$ / 520.00
1 pc	Front corner panel	Damaged / distorted	\$ 250.00	\$ x R 250.00
1 pc	Front bumper assy	Warped / deformed	\$ 750.00	\$ x R 750.00
2 pcs	Front bumper bracket	Bent / distorted	\$ 100.00	\$ x nn 100.00
1 pc	Front R/H door assy	Damaged	\$ 1,750.00	\$ / 1,750.00
1 pc	Front R/H door pillar	Bent / distorted - repair	\$ 789.10	\$ -
1 pc	Front R/H door weatherstrip	Warped / deformed	\$ 140.00	\$ x nn 140.00
1 pc	Front door inner step garnish	deformed	\$ 110.00	\$ x nn 110.00
Parts Sub-Total			\$ 4,409.10	\$ 3,620.00
Discount 25.00%			\$ 1,102.28	\$ 905.00
			\$ 3,306.83	\$ 2,715.00

Vehicle Number : GBD4523L

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 pc	Front door company sticker	necessary	\$ 80.00	\$ 50 / 80.00
Special Nett Sub-Total			\$ 80.00	\$ 80.00
Spare Parts Total			\$ 3,386.83	\$ 2,795.00

## LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 3,386.83	\$ 2,795.00
1	To transfer front door components to new doors.	\$ 180.00	\$ 50 / 150.00
2	To remove/reinstall seat, upholstery, trims & garnish to assist repairs.	\$ 150.00	\$ x 120.00
3	Labour charges to repair and panel beat frt fender inner panels, chassis n re-align frt pillars, cutting/welding and replacing the above mentioned parts.	\$ 1,400.00	\$ 400 1,200.00
4	To putty, apply primer & spray-paint the affected areas.	\$ 1,000.00	\$ 500 800.00
5	To apply rust-proofing on repaired/replaced panels.	\$ 150.00	\$ 30 120.00
	Total	\$ 6,266.83	\$ 5,185.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 4,150.00



Fong Kok Heng  
Qualified Appraiser



4 days