



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN:ERIC WOO

INV No. AC2503446

INV Date 02/06/2025

Reference CD/LPC24080176/Kpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 1160Z
Insured Veh. SLZ 4525Y
Claim No. 24/24/24/VP05/029679
Policy No. Z24VP05035367
Accident Date 11/08/2024
Inspection Date 13/08/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24080176/Kpa3q2
300 BEACH ROAD	Date:	07/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SLZ 4525Y	Veh. Inspected	SMG 1160Z
Policy No.	Z24VP05035367	Coverage	0
Claim No.	24/24/24/VP05/029679	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	13/08/2024

2. Vehicle Details

Make & Model	HONDA CIVIC 1.6 VTI CVT	C.C	1597
Engine No.	R16B25502458	Year of Reg.	30/01/2019
Chassis No.	MRHFC5650JT002077	Colour	METALLIC BLACK
Odometer	105878 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R18	BRIDGESTONE	8
L/H Front Tyre	225/45R18	BRIDGESTONE	6
R/H Rear Tyre	225/45R18	BRIDGESTONE	8
L/H Rear Tyre	225/45R18	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/08/2024	Inspection Date	13/08/2024
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 1160Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	HEADLAMP RH	MTG CRACKED	\$1,985.00	\$1,129.20
2	HEADLAMP LOWER BRACKET RH	TO REPAIR SEE LABOUR	\$220.00	\$0.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	\$598.00	\$0.00
1	FRONT FENDER LAMP RH	SERVICEABLE	\$280.00	\$0.00
1	FOG LAMP OUTER GARNISH RH	CUT	\$323.00	\$95.30
1	FRONT FENDER UNDERSHIELD RH (ADDITIONAL)	CRACKED	\$298.00	\$89.40
	LESS 20.00% DISCOUNT		(\$740.80)	(\$262.78)
			\$2,963.20	\$1,051.12

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER (SPORT) (SN)	CRACKED	\$2,000.00	\$1,600.00
1	FRONT RIM RH (SN)	SERVICEABLE	\$900.00	\$0.00
1	FRONT BUMPER LOWER GARNISH (SN)	MTG CRACKED	\$800.00	\$600.00
1	FRONT BUMPER LOWER SKIRTING (BASE) (SN) (ADDITIONAL)	REPEATED	\$650.00	\$0.00
10	FRONT BUMPER CLIPS (SN) (ADDITIONAL)	NECESSARY	\$45.00	\$45.00
10	FRONT FENDER UNDERSHIELD CLIPS RH (SN) (ADDITIONAL)	NECESSARY	\$45.00	\$45.00
			\$4,440.00	\$2,290.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF HEADLAMP LOWER BRACKET RH AND FRONT FENDER RH .		\$1,000.00	\$300.00
	ANTI RUST	NOT NECESSARY	\$120.00	\$0.00
	CHECK WIRING SYSTEM FORCUS LAMP ETC		\$120.00	\$20.00
	TO DO SPRAY PAINTING ON ACCIDENT AREA		\$1,000.00	\$400.00
			\$2,240.00	\$720.00

GRAND TOTAL	\$9,643.20	\$4,061.12
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,100.00
---	--	-------------------

Report Ref No: CD/LPC24080176/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z




PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z



PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z



PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z



PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z



PHOTOGRAPHS FOR VEHICLE NO. : SMG 1160Z

