



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKT 2045Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BOOT LID 02 LOGO	NOT NECESSARY	\$60.00	\$0.00
1	REAR BOOT LID VOLVO LOGO	NOT NECESSARY	\$100.00	\$0.00
1	REAR BOOT LID S60 LOGO	NOT NECESSARY	\$85.00	\$0.00
1	REAR BUMPER	DEFORMED	\$1,688.00	\$1,440.00
2	REAR BUMPER SIDE BRACKET @\$188.00	NOT NECESSARY	\$376.00	\$0.00
2	REAR BUMPER SIDE RETRAINER @\$225.00	NOT NECESSARY	\$450.00	\$0.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	\$155.00	\$0.00
1	REAR BUMPER LOWER LIP	DEFORMED	\$588.00	\$486.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	\$1,126.00	\$0.00
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	\$322.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$1,250.00	\$0.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	\$363.00	\$0.00
1	REAR SPARE TIRE PANEL TOP COVER	NOT NECESSARY	\$655.00	\$0.00
1	REAR EXHAUST ALUMINIUM COVER	CUT	\$250.00	\$165.00
1	REAR BUMPER CENTER BUMPER	DEFORMED	\$850.00	\$645.00
	<b>LESS 0.00 / 10.00% DISCOUNT</b>		\$0.00	(\$273.64)
			<b>\$8,318.00</b>	<b>\$2,462.76</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	\$800.00	\$200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$65.00	\$50.00
			<b>\$865.00</b>	<b>\$250.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & RE-FIX CUSHION	NOT NECESSARY	\$120.00	\$0.00
	TO REMOVE & RE-FIX REVERSE SENSOR		\$120.00	\$60.00
	TO CHECK WIRING SYSTEM	NOT NECESSARY	\$60.00	\$0.00
	TUFF KOTE	NOT NECESSARY	\$120.00	\$0.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$600.00	\$200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY PAINTING		\$600.00	\$300.00
			\$1,620.00	\$560.00
GRAND TOTAL			\$10,803.00	\$3,272.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,600.00
Report Ref No: CS/LIP24080178/Rqh3e2				

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,300.00=NETT VALUE: \$4,700.00

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.