



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBB 8320P

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE (N)	DENTED/BENT	\$1,350.00	\$1,350.00
1	TAILGATE LOCK - LH (N)	NOT NECESSARY	\$185.00	\$0.00
1	TAILGATE STOPPER - LH(N)	CUT	\$22.00	\$22.00
1	TAILGATE SEAL (N)	TORN	\$18.00	\$18.00
2	TAILGATE HINGES @\$85.00 (N)	NOT NECESSARY	\$170.00	\$0.00
1	TAILGATE CHECKER - LH (N)	NOT NECESSARY	\$115.00	\$0.00
1	TAILGATE LOWER MEMBER (N)	TO REPAIR SEE LABOUR	\$486.00	\$0.00
1	TAILLAMP - LH (N)	BROKEN	\$293.00	\$293.00
1	TAILLAMP PANEL - LH (N)	DENTED/BENT	\$155.00	\$155.00
1	REAR FENDER - LH (N)	TO REPAIR SEE LABOUR	\$1,850.00	\$0.00
1	REAR FENDER REFLECTOR - LH (N)	BROKEN	\$82.00	\$82.00
	LESS 10.00%		(\$472.60)	(\$192.00)
			\$4,253.40	\$1,728.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILGATE ALUMINIUM BOARD (SN)	TO REPAIR SEE LABOUR	\$450.00	\$0.00
1	REAR STICKER "70 KM/H" (SN)	NECESSARY	\$10.00	\$10.00
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	\$280.00	\$0.00
			\$740.00	\$10.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESPRAY UNDERCOATING		\$100.00	\$40.00
	TO CHECK REAR WIRING		\$50.00	\$20.00
	TO REMOVE, REFIX REAR REVERSE SENSOR		\$80.00	\$30.00
	TO RESPRAY PAINTING AND ETC		\$900.00	\$880.00
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOWER MEMBER AND REAR FENDER - LH		\$900.00	\$800.00
			\$2,030.00	\$1,770.00
GRAND TOTAL			\$7,023.40	\$3,508.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,800.00
--	---	--	-------------------

Report Ref No: CS/INC24080179/Uvh3

TOTAL FOR SPARE PARTS: \$ 4,993.40 \$ 1,738.00
TOTAL FOR LABOUR : \$ 2,030.00 \$ 1,770.00
TOTAL REPAIR COST: \$ 7,023.40 \$ 3,508.00

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.