

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24080184/RVP3E2**Date:** 03/10/2024REFERENCEInsured/Claimant: JALALUDDIN TRAVEL & SERVICES PTE LTD
Date of Loss: 10/08/2024Policy No: 7220007847-02
Nature of Claim: OD Claim No: 1490749278SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE419J	Engine No:	DPCD33433
Make & Model:	AUDI Q2, 1.5 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA1MA035451
Reg. Date:	27/01/2022 (Man. Year: 2021)	Odometer:	47546 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$141,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55Z R17	Rear Tyre Size:	215/55Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,841.00	8,016.80	5,824.20	42.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	2,502.00	3,350.00	57.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,693.00	10,518.80	9,174.20	46.59
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	18,893.00	9,718.80	9,174.20	48.56
+ GST 9.00/9.00% (\$\$)	1,700.37	874.69	825.68	48.56
Nett Amount (\$\$)	20,593.37	10,593.49	9,999.88	48.56

INSPECTION

Date of Assignment:	13/08/2024	
Date Inspected:	14/08/2024	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,575.00 FS	*1,260.00 FS
2	1		*FRONT BUMPER ADAPTOR - RH	Serviceable	54.00 FS	*- FS
3	1		*FRONT BUMPER TRIM - RH	Cut	116.00 FS	*92.80 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	114.00 FS	*90.80 FS
5	1		*FRONT PARKING AID SENSOR BRACKET - RH	Not Necessary	36.00 FS	*- FS
6	1		*FRONT BUMPER LOWER COVER	Cut	127.00 FS	*101.60 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	195.00 FS	*- FS
8	2		*FRONT WHEEL SPOILER - LH / RH	Serviceable	86.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Scratched	374.00 FS	*298.80 FS
10	1		*FRONT BUMPER ADAPTOR - RH	Serviceable	54.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	1,734.00 FS	*- FS
12	1		*RADIATOR GRILLE STRIKER PLATE	Serviceable	236.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - RH	Serviceable	45.00 FS	*- FS
14	1		*LED HEADLIGHT - RH	Broken	6,915.00 FS	*5,532.00 FS
15	1		*LED HEADLIGHT POWER MODULE - RH	Serviceable	904.00 FS	*- FS
16	1		*LED HEADLIGHT MOUNTING - RH	Serviceable	147.00 FS	*- FS
17	1		*LIFT CYLINDER - RH	Not Necessary	170.00 FS	*- FS
18	1		*LIFT CYLINDER HOSE - RH	Not Necessary	97.00 FS	*- FS
19	2		*FRONT WHEEL ARCH COVER - LH / RH	N/S Necessary / O/S Cracked	802.00 FS	*640.80 FS
20	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,841.00 8,016.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$)			5,852.00	2,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >