



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SDU 1155Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT DOOR ASSY	BENT	\$852.00	\$852.00
1	FRT DOOR BLACK STICKER	NECESSARY	\$78.00	\$78.00
1	FRT DOOR HANDLE OUTER	SERVICEABLE	\$153.40	\$0.00
1	REAR DOOR ASSY	TO REPAIR SEE LABOUR	\$752.10	\$0.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$542.70	\$0.00
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$186.00)
			\$2,378.20	\$744.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR ASSY AND REAR BUMPER		\$800.00	\$550.00
	SPRAY PAINTING		\$1,100.00	\$800.00
	CHECK WIRING		\$40.00	\$20.00
	TRANSFER DOOR MECHANISM		\$150.00	\$60.00
	TUFF COAT		\$80.00	\$30.00
			\$2,170.00	\$1,460.00

GRAND TOTAL			\$4,548.20	\$2,204.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,750.00

Report Ref No: CS3/SPF24080187/Kqp3

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,750-\$4,000

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.