



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS3/SPF24080187/Kqp3
ACCIDENT CLAIMS SECTION	Date:	03/09/2024
(SPORE POLICE FORCE)		
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	QX 3278T	Veh. Inspected	SDU 1155Y
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/039(LK)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	12/08/2024

2. Vehicle Details

Make & Model	HONDA CITY (A)	C.C	1497
Engine No.	L15Z12722094	Year of Reg.	29/06/2016
Chassis No.	MRHGM6660GP000532	Colour	METALLIC GREY
Odometer	78315 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/55R16	YOKOHAMA	8
L/H Front Tyre	185/55R16	YOKOHAMA	8
R/H Rear Tyre	185/55R16	YOKOHAMA	8
L/H Rear Tyre	185/55R16	YOKOHAMA	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/08/2024	Inspection Date	20/08/2024 (10:43)
Survey held at	T & S MOTOR SERVICE - BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days