



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CS/FCI24060102/Uvh3	
		Date:	25/07/2024	
		Code:	FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4285T	Veh. Inspected	SLC 4188H	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24005280MFCT	Excess	\$0.00	
Assign From	CAROLINE CABRERA	Assign Date	14/06/2024	
2. Vehicle Details				
Make & Model	TOYOTA CAMRY (A)	C.C	2362	
Engine No.	2AZE112219	Year of Reg.	26/09/2008	
Chassis No.	MR053BK4007029382	Colour	GREY	
Odometer	236784 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	245/35ZR19	ROVELO	6	
L/H Front Tyre	245/35ZR19	ROVELO	6	
R/H Rear Tyre	275/30ZR19	TOURADOR	6	
L/H Rear Tyre	275/30ZR19	TOURADOR	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/06/2024	Inspection Date	14/06/2024	
Survey held at	WE GARAGE - 1 KAKI BUKIT AVE 6, #02-11 AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT.				
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days				