

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ECICS Limited  
10 Eunios Road 8, #09-04A Singapore Post Centre  
Singapore 408600**Our File No:** CS/ICS24080194/RVP3E2  
**Date:** 27/09/2024REFERENCEInsured/Claimant: YEO BOON KWANG Policy No: MPC23A00385000  
Date of Loss: 24/07/2024 Nature of Claim: OD Claim No: DMPC2400953H/CTDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SCX60P**  
Make & Model: LEXUS RX200T, 2.0 (A) Engine No: 8ARW686428  
Reg. Date: 29/12/2017 (Man. Year: 2017) Chassis No: JTJBAMCA102040798  
Colour: Grey Odometer: 95282 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$123,000.00  
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 235/55 R20 Rear Tyre Size: 235/55 R20  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	18,290.72	12,521.25	5,769.47	31.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,430.80	10,886.40	3,544.40	24.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>32,721.52</b>	<b>23,407.65</b>	<b>9,313.87</b>	<b>28.46</b>
<b>+ GST 9.00/9.00% (S\$)</b>	<b>2,944.94</b>	<b>2,106.69</b>	<b>838.25</b>	<b>28.46</b>
<b>Nett Amount (S\$)</b>	<b>35,666.46</b>	<b>25,514.34</b>	<b>10,152.12</b>	<b>28.46</b>

INSPECTIONDate of Assignment: 14/08/2024 Present Location: Borneo Motors (S) Pte Ltd (Pandan)  
Date Inspected: 14/08/2024 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462  
Estimated Period of Repair: 11.0 days**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2024)	
<b>Parts:</b> M1-SUV	LEXUS RX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SCX60P)		
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	T21000-20	*SIKA 182010 SIKA TACK GO! (BLA	Necessary	108.00 FL	*108.00 FL
2	1	T21000-22	*SIKA 207. G+P ADHESIVE PRIMER	Necessary	200.00 FL	*200.00 FL
3	1	T08826-08115	*PANEL BONDING AD	Necessary	267.20 FL	*267.20 FL
4	20	L90269-04051	*RIVET	Necessary	44.00 FL	*44.00 FL
5	20	T90269-06013	*RIVET	Necessary	56.00 FL	*56.00 FL
6	1	L52159-48931	*COVER RR BUMPER	Not Necessary	1,582.60 FL	*- FL
7	1	L61601-48050	*PANEL SUB-ASSY	Bent	2,639.00 FL	*2,639.00 FL
8	1	L65637-48070	*LINER RR WHEEL	Not Necessary	493.60 FL	*- FL
9	1	L62904-48030	*DUCT SUB-ASSY	Not Necessary	213.20 FL	*- FL
10	1	L62710-48310	*WINDOW ASSY	Necessary	392.80 FL	*392.80 FL
11	1	L67001-48160	*PANEL SUB-ASSY FR	Bent	3,614.30 FL	*3,614.30 FL
12	1	L67861-48110	*WEATHERSTRIP FR	Not Necessary	392.80 FL	*- FL
13	1	L75921-48060	*TAPE BLACK OUT	Necessary	23.10 FL	*23.10 FL
14	1	L75985-48050	*STRIPE FR DOOR	Necessary	95.60 FL	*95.60 FL
15	1	L75965-48010	*STRIPE FR DOOR	Necessary	38.00 FL	*38.00 FL
16	1	L68610-48080	*CHECK ASSY FR DOOR	Not Necessary	381.60 FL	*- FL
17	1	L67003-48190	*PANEL SUB-ASSY RR	Bent	3,194.80 FL	*3,194.80 FL
18	1	L67871-48080	*WEATHERSTRIP RR	Not Necessary	347.00 FL	*- FL
19	1	L75977-48050	*STRIPE RR DOOR	Necessary	45.80 FL	*45.80 FL
20	1	L75987-48070	*STRIPE RR DOOR	Necessary	60.60 FL	*60.60 FL
21	1	L75953-48030	*TAPE BLACK OUT RR	Necessary	52.80 FL	*52.80 FL
22	1	L67895-48041	*WEATHERSTRIP RR	Necessary	58.10 FL	*58.10 FL
23	1	L67857-48032	*PROTECTOR RR DOOR	Scratched	200.80 FL	*200.80 FL
24	1	L68630-48080	*CHECK ASSY RR DOOR	Not Necessary	381.60 FL	*- FL
25	1	L75071-48100	*MOULDING SUB-ASSY	Scratched	761.60 FL	*761.60 FL
26	1	L75075-48140	*MOULDING SUB-ASSY	Scratched	600.20 FL	*600.20 FL
27	1	L75077-48010	*MOULDING SUB-ASSY	Scratched	126.20 FL	*126.20 FL
28	1	L75605-48020	*MOULDING SUB-ASSY	Scratched	194.10 FL	*194.10 FL
29	1	L75873-48020	*MOULDING QUARTER	Necessary	97.60 FL	*97.60 FL
30	1	L75850-48040	*MOULDING ASSY BODY	Not Necessary	761.60 FL	*- FL
31	14	L75867-30120	*CLIP ROCKER PANEL	Not Necessary	211.40 FL	*- FL
32	4	L75857-48010	*COVER ROCKER PANEL	Not Necessary	21.60 FL	*- FL
33	1	L75865-48040	*PROTECTOR ROCKER	Not Necessary	60.50 FL	*- FL
34	1	L75755-48040	*MOULDING FR DOOR	Necessary	104.30 FL	*104.30 FL
35	1	L75707-48030	*MOULDING SUB-ASSY	Necessary	135.80 FL	*135.80 FL
36	1	L42611-48851	*WHEEL DISC	Scratched	4,776.80 FL	*4,776.80 FL
37	1	L88162-48032	*SENSOR BLIND SPOT	Not Necessary	3,394.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>26,129.60</b>	<b>17,887.50</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$\$)</b>	7,838.88	5,366.25
<b>Total Parts (\$\$)</b>	<b>18,290.72</b>	<b>12,521.25</b>

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SUNDRIES	New	100.00	50.00
2	TO CHECK WIRING AND CONDUCT WATER L	New	192.00	192.00
3	TO REMOVE AND REINSTALL REAR BUMPER	New	192.00	192.00
4	TO RESET ECU & REPROGRAMME	New	192.00	192.00
5	TO CONDUCT ADJUSTMENT ON REAR BLI	New	192.00	192.00
6	TO REMOVE AND REINSTALL REAR SEAT A	New	768.00	768.00
7	TO REPLACE TYRE RIM AND CONDUCT WHE	New	192.00	192.00
8	TO CONDUCT WHEEL ALIGNMENT ADJUSTME	New	192.00	192.00
9	RENEW REAR RHS QUATER GLASS	New	384.00	384.00
10	TO SUPPLY & INSTALL QUATER GLASS 3M	New	230.00	230.00
11	TO REMOVE AND REINSTALL BOTH RHS'S	New	1,536.00	1,536.00
12	SUPPLY SEALANT (NETT)	New	200.00	200.00
13	TO REPLACE AND REPAIR ON ACCIDENT A	New	6,144.00	4,608.00
14	TO SPRAY PAINTING ON ACCIDENT AFFEC	New	3,916.80	1,958.40
<b>Gross Labour Cost (S\$)</b>			<b>14,430.80</b>	<b>10,886.40</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >