



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHB 9529C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	MIRROR ASSY, OUTER REAR VIEW, RH	BROKEN	\$1,814.09	\$1,814.09
	LESS 25.00% DISCOUNT		(\$453.52)	(\$453.52)
			\$1,360.57	\$1,360.57

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	NOT NECESSARY	\$250.00	\$0.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION & LABOUR TO CHANGE ABOVE ITEM		\$1,000.00	\$140.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED		\$170.00	\$20.00
			\$1,420.00	\$160.00

<b>GRAND TOTAL</b>			<b>\$2,780.57</b>	<b>\$1,520.57</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$1,200.00</b>

Report Ref No: CS/FCI24060103/Kvh3e2

**KSC**

KENNETH KONG SENG CHEONG