

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080208/RMA3Q2**Date:** 19/11/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0002021
Claimant Vehicle No : SNJ9835E **Insured Vehicle No :** PD11H
 Date of Loss: 06/08/2024 Nature of Claim: TP Claim No: MFL2024D0009322

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNJ9835E**
 Make & Model: SKODA SUPERB, 2.0 AMBITION SA (A) Engine No: CZP248430
 Reg. Date: 24/03/2021 (Man. Year: 2020) Chassis No: TMBBM7NPOL7074641
 Colour: Grey Odometer: 54689 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R19 Rear Tyre Size: 245/40Z R19
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,484.02	6,888.86	6,595.16	48.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,847.00	4,731.00	3,116.00	39.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,331.02	11,619.86	9,711.16	45.53
+ GST 9.00/9.00% (S\$)	1,919.79	1,045.79	874.00	45.53
Nett Amount (S\$)	23,250.81	12,665.65	10,585.16	45.53
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		13,092.90		

INSPECTION

Date of Assignment: 15/08/2024
 Date Inspected: 15/08/2024 Inspected At: Volkswagen Group Singapore Pte Ltd (HQ)
 247 ALEXANDRA ROAD
 Singapore 159934
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2024)
Parts:	144	SKODA SUPERB 2.0 AMBITION SA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ9835E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Repair	2,969.15 FS	*- FS
2	1		*SKODA EMBL	Necessary	51.41 FS	*51.41 FS
3	1		*COVER FOR FRT BUMPER	Deformed	2,404.82 FS	*2,404.82 FS
4	1		*SENSOR BRACKET	Necessary	39.33 FS	*39.33 FS
5	1		*SENSOR BRACKET	Necessary	39.33 FS	*39.33 FS
6	1		*SENSOR BRACKET	Necessary	39.33 FS	*39.33 FS
7	1		*SENSOR BRACKET	Necessary	39.33 FS	*39.33 FS
8	1		*ANSCHLUSSBLECH RADIATOR GRILLE TOP COVER	Cut	224.98 FS	*224.98 FS
9	1		*STICKER OIL COMPLY WITH	Not Necessary	26.06 FS	*- FS
10	1		*STICKER AC REFRIGERAN	Necessary	18.72 FS	*18.72 FS
11	1		*STICKER OVERFILLED ENGIN	Necessary	16.45 FS	*16.45 FS
12	2		*RIVET	Necessary	4.10 FS	*4.10 FS
13	1		*GRILLE RADIATOR GRILLE	Cracked	801.30 FS	*801.30 FS
14	1		*TRIM RADIATOR GRILLE CTR TRIM	Cracked	281.22 FS	*281.22 FS
15	1		*CONTROL UNIT WITH SOFTWARE RADAR SENSOR	Shorted	2,201.77 FS	*2,201.77 FS
16	1		*COVER STRI RADIATOR GRILLE MLDG CHROM	Cracked	425.40 FS	*425.40 FS
17	1		*COOLING AI BUMPER CTR LOWER GRILLE	Cracked	154.99 FS	*154.99 FS
18	1		*ZIARIEISTE BUMPER CTR LOWER GRILLE MLDG(BLACK)	Not Necessary	157.45 FS	*- FS
19	1		*REINFORCEM	Not Necessary	987.80 FS	*- FS
20	1		*BUFFER REINFORCEMENT FOAM	Cracked	70.38 FS	*70.38 FS
21	1		*AIR DUCT AIR GUIDE (UPPER)	Not Necessary	62.60 FS	*- FS
22	1		*HEADLIGHT LH	Not Necessary	2,371.07 FS	*- FS
23	1		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	Not Necessary	21.03 FS	*- FS
24	1		*FRT NUMBER PLATE	Deformed	76.00 FS	*76.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,484.02 6,888.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	3,192.00	1,596.00
2	SPRAY PAINTQ	New	3,040.00	1,520.00
3	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	266.00	266.00
4	B&P DIAGNOSIS AND PROGRAMMING	New	456.00	456.00
5	TO ALIGN HEADLIGHT	New	95.00	95.00
6	RADAR SENSOR CALIBRATION	New	798.00	798.00
Gross Labour Cost (\$\$)			7,847.00	4,731.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >