



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNF 7371K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BUCKLED/DENTED	\$900.00	\$871.20
1	FRONT BUMPER RETAINER LHS	SERVICEABLE	\$50.00	\$0.00
1	FRONT BUMPER LOWER GRILLE	DENTED	\$200.00	\$200.00
1	FRONT BUMPER LOWER SPOILER	DISTORTED	\$370.00	\$370.00
1	DAYLIGHT LHS	SERVICEABLE	\$520.00	\$0.00
1	DAYLIGHT GARNISH LHS	MTG CRACKED	\$70.00	\$70.00
1	HEADLAMP LHS	MTG CRACKED	\$2,400.00	\$2,180.40
1	HEADLAMP BRACKET LHS	SERVICEABLE	\$70.00	\$0.00
1	FRONT GRILLE ASSY	MTG CRACKED	\$1,050.00	\$1,025.10
1	FRONT GRILLE TOP CHROME	SERVICEABLE	\$200.00	\$0.00
1	FRONT SENSOR LHS	SERVICEABLE	\$350.00	\$0.00
1	FRONT REINFORCEMENT	TO REPAIR SEE LABOUR	\$420.00	\$0.00
1	FRONT WHEELARCH MOULDING LHS	SERVICEABLE	\$280.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,376.00)	(\$943.34)
			\$5,504.00	\$3,773.36

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$60.00	\$60.00
			\$60.00	\$60.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT		\$1,600.00	\$300.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED		\$1,600.00	\$220.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS		\$100.00	\$15.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	NOT NECESSARY	\$100.00	\$0.00
	DIAGNOSTIC CHECK		\$100.00	\$60.00
	REMOVE & REFIT FRONT SENSORS		\$100.00	\$60.00
			\$3,600.00	\$655.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$9,164.00	\$4,488.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,600.00
Report Ref No: CS/SPF24080213/Knp3m4			

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.