

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24080222/RQP3E2**Date:** 27/09/2024REFERENCE

Insured/Claimant:	LOH KIA IM PATRICIA	Policy No:	7230009648	
Date of Loss:	14/08/2024	Nature of Claim:	OD	Claim No: 2308846820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKS317G</b>		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	DFY356948
Reg. Date:	30/01/2023 (Man. Year: 2022)	Chassis No:	WAUZZZF32P1012106
Colour:	Grey	Odometer:	11174 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$183,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,259.00	7,201.92	5,057.08	41.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,372.00	3,092.00	6,280.00	67.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>21,631.00</b>	<b>10,293.92</b>	<b>11,337.08</b>	<b>52.41</b>
<b>- Excess (\$\$)</b>	400.00	400.00	0.00	0.00
<b>(\$\$)</b>	21,231.00	9,893.92	11,337.08	53.40
<b>+ GST 9.00/9.00% (\$\$)</b>	1,910.79	890.45	1,020.34	53.40
<b>Nett Amount (\$\$)</b>	<b>23,141.79</b>	<b>10,784.37</b>	<b>12,357.42</b>	<b>53.40</b>

INSPECTION

Date of Assignment:	16/08/2024	
Date Inspected:	15/08/2024	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Repair	1,537.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT - LH	Not Necessary	74.00 FS	*- FS
3	1		*FRONT WHEEL ARCH COVER - LH	Necessary	639.00 FS	*511.20 FS
4	1		*FRONT DOOR - LH	Bent	3,215.00 FS	*2,572.00 FS
5	1		*FRONT DOOR OUTER SEAL - LH	Necessary	206.00 FS	*164.80 FS
6	1		*FRONT DOOR CATCH - LH	Bent	150.00 FS	*120.00 FS
7	1		*FRONT DOOR HINGE HALVES - LH UPPER	Not Necessary	59.00 FS	*- FS
8	1		*FRONT DOOR HINGE HALVES - LH UPPER	Not Necessary	59.00 FS	*- FS
9	1		*FRONT DOOR HINGE HALVES - LH LOWER	Not Necessary	59.00 FS	*- FS
10	1		*FRONT DOOR HINGE HALVES - LH LOWER	Not Necessary	59.00 FS	*- FS
11	1		*FRONT DOOR CORNER TRIM - LH	Scratched	57.00 FS	*45.20 FS
12	1		*FRONT DOOR SEALING ELEMENT - LH	Not Necessary	31.00 FS	*- FS
13	1		*FRONT WINDOW SOLT SEAL - LH	Not Necessary	280.00 FS	*- FS
14	1		*FRONT DOOR LOWER COVER - LH	Scratched	438.00 FS	*350.40 FS
15	1		*FRONT DOOR WINDOW	Not Necessary	296.00 FS	*- FS
16	1		*FRONT WING MIRROR MOUNTING - LH	Cracked	2,560.00 FS	*2,048.00 FS
17	1		*FRONT WING MIRROR CAP - LH	Missing	269.00 FS	*215.20 FS
18	1		*FRONT WING MIRROR GLASS - LH	Missing	1,038.00 FS	*830.40 FS
19	1		*FRONT WINDOW TRIM STRIP - LH	Not Necessary	320.00 FS	*- FS
20	1		*REAR DOOR COVER - LH	Scratched	413.00 FS	*330.00 FS
21	1		*SUNDRIES	Necessary	500.00 FS	*14.72 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,259.00 7,201.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	400.00
3	TO REMOVE AND REINSTALL FRONT BUMPER. TO DISMANTLE AND RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	500.00
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT AND REAR DOORS, LHS FRONT AND REAR DOOR LOWER COVER AND LHS WING MIRROR COVER	New	4,200.00	1,900.00
5	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR GLASS	New	400.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,372.00</b>	<b>3,092.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >