



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMU 775H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER O/S	CUT/TORN	\$1,200.00	\$844.60
1	REAR BUMPER REINFORCEMENT	DENTED/BENT	\$2,800.00	\$1,300.00
1	REAR BUMPER OUTER BLACK COVER	GRAZED	\$3,500.00	\$2,967.50
1	REAR BUMPER DIFFUSER	CUT	\$1,600.00	\$890.90
	LESS 0.00 / 5.00% DISCOUNT		\$0.00	(\$300.15)
			\$9,100.00	\$5,702.85

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NO. PLATE (SN)	BENT	\$60.00	\$40.00
			\$60.00	\$40.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR REMOVING REAR BUMPER AND REINFORCEMENT TO FACILITATE AND REPLACEMENT OF PARTS		\$400.00	\$400.00
	TO RESPRAY REAR BUMPER AND REAR TAILGATE		\$500.00	\$500.00
			\$900.00	\$900.00

GRAND TOTAL			\$10,060.00	\$6,642.85
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$5,300.00
--	---	--	--	-------------------

Report Ref No: CS/INC24080229/Uqh3

TOTAL FOR SPARE PARTS: \$ 9,160.00 \$ 5,742.85
TOTAL FOR LABOUR : \$ 900.00 \$ 900.00
TOTAL REPAIR COST: \$10,060.00 \$ 6,642.85

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.