

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24060106/UUA3Q2
Date: 19/09/2024

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900243908
Claimant Vehicle No :	SBQ2688P	Insured Vehicle No :	SJJ1516B
Date of Loss:	12/06/2024	Nature of Claim:	TP
		Claim No:	2239538805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBQ2688P	Engine No:	1ZRY221785
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)	Chassis No:	MR053REH104540792
Reg. Date:	24/11/2015 (Man. Year: 2015)	Odometer:	50542 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,094.00	4,055.77	12,038.23	74.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	1,860.00	3,800.00	67.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,754.00	5,915.77	15,838.23	72.81
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	21,754.00	4,100.00	17,654.00	81.15
+ GST 9.00/9.00% (S\$)	1,957.86	369.00	1,588.86	81.15
Nett Amount (S\$)	23,711.86	4,469.00	19,242.86	81.15
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,871.18		

INSPECTION

Date of Assignment:	14/06/2024	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	01/07/2024 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	4.0 days	Singapore 489977

Adjuster: NA MENG YAN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,294.10 FL	*1,294.10 FL
2	1		*BOOTLID HINGE LH	Not Necessary	94.80 FL	*- FL
3	1		*BOOTLID HINGE RH	Not Necessary	94.80 FL	*- FL
4	1		*BOOTLID INNER TRIMBOARD	Not Necessary	494.30 FL	*- FL
5	1		*BOOTLID RUBBER	Twisted	238.20 FL	*238.20 FL
6	1		*BOOTLID LOCK	Serviceable	542.40 FL	*- FL
7	1		*BOOTLID CABLE	Not Necessary	105.30 FL	*- FL
8	1		*BOOTLID LAMP RH	Cracked	521.80 FL	*305.40 FL
9	1		*BOOTLID LAMP LH	Cracked	521.80 FL	*305.40 FL
10	1		*BOOTLID OUTER CHROME	Not Necessary	330.80 FL	*- FL
11	1		*BOOTLID EMBLEM	Necessary	64.90 FL	*64.90 FL
12	1		*BOOTLID LOGO-COROLLA	Necessary	55.70 FL	*55.70 FL
13	1		*BOOTLID LOGO-ALTIS	Necessary	62.00 FL	*62.00 FL
14	1		*BOOTLID LOCK COVER (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*BOOTLID LOWER LOCK	Not Necessary	20.90 FL	*- FL
16	1		*END PANEL	Dented	1,008.40 FL	*1,008.40 FL
17	1		*END PANEL TOP GARNISH	Twisted	327.80 FL	*327.80 FL
18	1		*SPARE TYRE PANEL	Repair	1,222.30 FL	*- FL
19	1		*SPARE TYRE PANEL TOP TRIMBOARD	Not Necessary	362.20 FL	*- FL
20	1		*REAR FLOOR PANEL SIDE PANEL RH	Not Necessary	37.80 FL	*- FL
21	1		*REAR FLOOR PANEL SIDE PANEL LH	Not Necessary	37.80 FL	*- FL
22	1		*SPARE TYRE SCREW	Not Necessary	32.90 FL	*- FL
23	1		*SPARE TYRE BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*TAIL LAMP RH	Cracked	510.80 FL	*510.80 FL
25	1		*TAIL LAMP LH	Not Necessary	510.80 FL	*- FL
26	1		*TAIL LAMP CLIP RH	Not Necessary	5.50 FL	*- FL
27	1		*TAIL LAMP CLIP LH	Not Necessary	5.50 FL	*- FL
28	1		*TAIL LAMP PANEL LH	Repair	151.30 FL	*- FL
29	1		*TAIL LAMP PANEL RH	Repair	151.30 FL	*- FL
30	1		*REAR FENDER LH	Repair	1,715.20 FL	*- FL
31	1		*REAR FENDER RH	Repair	1,715.20 FL	*- FL
32	1		*REAR FENDER INNER TRIMBOARD RH	Not Necessary	447.70 FL	*- FL
33	1		*REAR FENDER INNER TRIMBOARD LH	Not Necessary	447.70 FL	*- FL
34	1		*REAR FENDER INNER AIR DUCT RH	Not Necessary	185.70 FL	*- FL
35	1		*REAR FENDER INNER AIR DUCT LH	Not Necessary	185.70 FL	*- FL
36	1		*REAR FENDER INNER SHIELD RH	Not Necessary	74.80 FL	*- FL
37	1		*REAR FENDER INNER SHIELD LH	Not Necessary	74.80 FL	*- FL
38	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
39	1		*REAR BUMPER	Dented / Deformed	828.80 FL	*636.80 FL
40	2		*REAR BUMPER RETAINER RH	Not Necessary	328.80 FL	*- FL
41	2		*REAR BUMPER RETAINER LH	Not Necessary	328.80 FL	*- FL
42	1		*REAR BUMPER BRACKET RH (NPA)	Not Necessary	0.00 FL	*- FL
43	1		*REAR BUMPER BRACKET LH (NPA)	Not Necessary	0.00 FL	*- FL
44	1		*REAR BUMPER REINFORCEMENT	Dented	598.20 FL	*598.20 FL
45	1		*REAR BUMPER SPONGE (NPA)	Not fitted	0.00 FL	*- FL
46	1		*REAR BUMPER REFLECTOR RH	Not Necessary	81.80 FL	*- FL
47	1		*REAR BUMPER REFLECTOR LH	Not Necessary	81.80 FL	*- FL
48	1		*REAR CHASSIS RH (NPA)	Not Necessary	0.00 FL	*- FL
49	1		*REAR CHASSIS LH (NPA)	Not Necessary	0.00 FL	*- FL
50	1		*REAR NUMBER LAMP RH	Not Necessary	89.20 FL	*- FL
51	1		*REAR NUMBER LAMP LH	Not Necessary	89.20 FL	*- FL
52	1		*REAR DOOR RH	Not Necessary	1,864.60 FL	*- FL
53	1		*REAR DOOR LH	Not Necessary	1,864.60 FL	*- FL
54	1		*REAR FENDER MUDFLAP LH	Not Necessary	71.60 FL	*- FL
55	1		*REAR FENDER MUDFLAP RH	Not Necessary	71.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR REMOTE CENTER LOCK SENSOR (NPA)	Not Necessary	0.00 FL	*- FL
57	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
58	1		*REAR NUMBER PLATE HOLDER	Serviceable	35.00 FS	*- FS
59	2		*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
60	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
61	1		*REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,082.00	5,407.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,988.00	1,351.93
Total Parts (\$\$)	16,094.00	4,055.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	2,500.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,800.00	900.00
3	ANTI-RUST COATING	New	300.00	50.00
4	WIRING	New	100.00	20.00
5	TO REMOVE & REFIT WINDSCREEN	New	180.00	0.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	30.00
7	TO REMOVE & REFIT CUSHION & UPHOLSTERY	New	200.00	60.00
8	TO REMOVE & REFIT FUEL TANK	New	250.00	0.00
9	FOUR WHEEL ALIGNMENT	New	180.00	0.00
Gross Labour Cost (\$\$)			5,660.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >