



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GT 8883C

Cost Plus				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BONNET (WCP)	BUCKLED	\$3,200.00	\$3,200.00
2	BONNET HINGE @\$180.00 (WCP)	DISTORTED	\$360.00	\$360.00
1	BONNET LOCK (WCP)	DISTORTED	\$225.00	\$225.00
2	HEADLAMP @\$890.00 (WCP)	MTG CRACKED	\$1,780.00	\$1,780.00
1	RADIATOR GRILLE BASE (WCP)	CRACKED	\$980.00	\$980.00
1	RADIATOR GRILLE SIDE GARNISH (WCP)	DISTORTED	\$200.00	\$200.00
1	FRONT BUMPER (WCP)	BENT	\$1,215.00	\$1,215.00
2	FRONT BUMPER SIDE RETAINER @\$75.00 (WCP)	DISTORTED	\$150.00	\$150.00
1	FRONT BUMPER LOWER GRILLE (WCP)	DENTED	\$260.00	\$260.00
1	FRONT BUMPER TOW COVER (WCP)	SERVICEABLE	\$125.00	\$0.00
2	FRONT BUMPER FOG LAMP @\$285.00 (WCP)	SERVICEABLE	\$570.00	\$0.00
2	FRONT BUMPER FOG LAMP COVER @\$350.00 (WCP)	SERVICEABLE	\$700.00	\$0.00
2	FRONT BUMPER DAY LIGHT @\$570.00 (WCP)	SERVICEABLE	\$1,140.00	\$0.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BUCKLED	\$1,180.00	\$1,180.00
1	AIR CON CONDENSER (WCP)	PUNCTURE	\$1,200.00	\$1,200.00
1	RADIATOR (WCP)	PUNCTURE	\$900.00	\$900.00
1	RADIATOR FAN ASSY (WCP)	SERVICEABLE	\$1,000.00	\$0.00
1	RADIATOR GRILLE CENTER COVER (WCP)	SERVICEABLE	\$650.00	\$0.00
1	FRONT SUPPORT PANEL BOTTOM (WCP)	BENT	\$1,100.00	\$1,100.00
1	CHARGING PORT BRACKET (WCP) (ADDITIONAL)	BENT	\$1,050.00	\$1,050.00
	<b>COST PLUS 15.00%</b>		\$2,697.75	\$2,070.00
			\$20,682.75	\$15,870.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT BUMPER RIVETS (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT NUMBER PLATE (SN)	BENT	\$45.00	\$45.00
			\$165.00	\$45.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND FOCUS HEADLAMP		\$60.00	\$20.00
	TO VACUUM, REOIL AND REGAS AIR CON		\$120.00	\$100.00
	TO BARRICADE VEHICLE, REMOVE SAFETY PLUG, ENSURE NO VOLTAGE IN VEHICLE BEFORE PROCEEDING WITH REPAIRS		\$500.00	\$280.00
	TO RESET EV SYSTEM USING DIAGNOSTIC SCANNER AND TEST DRIVE		\$480.00	\$250.00
	TO RECHARGE BATTERY		\$350.00	\$200.00
	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT / REWELD FRONT SUPPORT PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME		\$800.00	\$600.00
	TO PUTTY AND SPRAY PAINTING ON ACCIDENT DAMAGE AREA		\$800.00	\$700.00
			\$3,110.00	\$2,150.00
<b>GRAND TOTAL</b>			<b>\$23,957.75</b>	<b>\$18,065.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>\$18,065.00</b>
	<b>LESS EXCESS</b>			<b>(\$500.00)</b>
	<b>NETT LIABILITY</b>			<b>\$17,565.00</b>
Report Ref No: CS/LPC24080235/Knh3e2				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.