

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080239/RUA3Q2
Date: 06/12/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0004658_02
Claimant Vehicle No : SKE2008J **Insured Vehicle No :** SGM6338K
 Date of Loss: 13/08/2024 Nature of Claim: TP Claim No: MPC2024D0009476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE2008J**
 Make & Model: BMW 216I, 1.5 GRAN TOURER (A) Engine No: 31036220B38A15A
 Reg. Date: 28/12/2020 (Man. Year: 2020) Chassis No: WBA6V120905S54983
 Colour: Gold Odometer: 43602 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,985.25	126.75	3,858.50	96.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	2,065.00	425.00	17.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,475.25	2,191.75	4,283.50	66.15
+ GST 9.00/9.00% (S\$)	582.77	197.26	385.51	66.15
Nett Amount (S\$)	7,058.02	2,389.01	4,669.01	66.15
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,541.19		

INSPECTION

Date of Assignment: 09/09/2024
 Date Inspected: 09/09/2024 Inspected At: Performance Motors Limited (HQ)
 303 Alexandra Road, Singapore
 Singapore 159941
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2024)
Parts: M1-MPV	BMW 216i 1.5 GRAN TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE2008J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*40.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	525.75 FS	*- FS
3	1		*SUPPORT	Not Necessary	86.70 FS	*- FS
4	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	172.60 FS	*- FS
5	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	172.60 FS	*- FS
6	1		*LEFT PROTECTION FOIL	Not Necessary	12.25 F	*- F
7	1		*RIGHT PROTECTION FOIL	Not Necessary	12.25 F	*- F
8	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	47.10 F	*- F
9	1		*REAR BUMPER TRIM STRIP (BLACK)	Scratched	86.75 F	*86.75 F
10	1		*REAR BUMPER PANEL PRIMED (LINES PDC)	Repair	1,132.45 F	*- F
11	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	22.60 F	*- F
12	4		*ULTRASONCI SENSOR	Not Necessary	1,564.20 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,985.25	126.75
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER INCLUDE ATTACHMENT ETC AND CARRYOUT NECESSARY REPAIRING WORK ON ACCIDENT DAMAGE AREA	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	1,038.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	177.00
Gross Labour Cost (\$)			2,490.00	2,065.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >