

09/AG224080244/Kgp3

C

ASS. REC. BY:

REF:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ C / Ink

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.B.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCU 7355 Yr Regn: 08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon
Make: Honda Civic C.C. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 186271 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: GIB7 1067160

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 9 mm	R/Bal. 9 mm
L/Bal. 9 mm	L/Bal. 9 mm
D.O.A. 13/8/24	D.O.I. 23/8/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/8 @ 3292.00 Cash (Red & 210, 6%)
(No Lump Sum)

Date/Time, File Pass to?

1) 28/8 11:15 AM ☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ 3292)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation: \$ - RS. \$ SI

Fuel: \$

Others: \$

TOTAL

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035494
Lim Chun Heng (Lin Junxing)

Page: 1 of 2
Your ref.: TP-SMN 5456H AGI
Job No.: 74650
Our ref: 24.08.19
Payment
Date: 15/8/2024

Attn

Vehicle No: SCU 735S
Vehicle Model : Honda Freed
Accident on ...: 13/8/2024

Not Notified
Repairing B4 part
\$3292.00 4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Tailgate	1,056.90	20.00	845.52 ✓
1.00	Set	Rear windscreen mouldings	67.20	20.00	53.76 ✓
1.00	Pc	Rear bumper	881.40	20.00	705.12 ✓
1.00	Pc	Rear end panel inner garnish	68.80	20.00	55.04 ✓
Labour & Misc:					
1.00		To dismantle+refix rear windscreen	140.00		140.00 120 ✓
1.00		To supply sealant	40.00		40.00 ✓
1.00		To dismantle+refix reversing camera+reversing sensors	80.00		80.00 ✓
1.00		To dismantle+refix rear floor panel carpet, etc	80.00		80.00 ✓
1.00		To straighten body, to knock dents on rear end panel, rear floor panel and renew parts	600.00		600.00 550 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035494
Lim Chun Heng (Lin Junxing)

Page: 2 of 2
Your ref.: TP-SMN 5456H AGI
Job No.: 74650
Our ref: 24.08.19
Payment:
Date: 15/8/2024

Attn

Vehicle No: SCU 735S
Vehicle Model : Honda Freed
Accident on ...: 13/8/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (Pearl white)	800.00		800.00 6601

Sub-Total 3,399.44
GST 9.00% 305.95
Total S\$ 3,705.39

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No: EST0035494
Lim Chun Heng (Lin Junxing)

Page: 1 of 1
Your ref.: TP-SMN 5456H AGI
Job No.: 74650
Our ref: 24.08.19
Payment:
Date: 26/8/2024

Attn

Vehicle No: SCU 735S
Vehicle Model : Honda Freed
Accident on ...: 13/8/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
SUPPLEMENTARY ITEM:					
1.00	Pc	Tailgate weatherstrip	<i>Dolly</i> 128.20	20.00	102.56 ✓

Sub-Total 102.56
GST 9.00% 9.23
Total S\$ 111.79

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."