

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24080246/UPA3Q2**Date:** 17/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100439576  
**Claimant Vehicle No :** AK2460Y **Insured Vehicle No :** SGE707K  
 Date of Loss: 27/07/2024 Nature of Claim: TP Claim No: 0139025539SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **AK2460Y**  
 Make & Model: VESPA VESPA, 150cc Engine No: 68775  
 Reg. Date: 01/07/1968 (Man. Year: 1968) Chassis No: 65796  
 Colour: Metallic Silver Odometer: 1317 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 3.50-8 Rear Tyre Size: 3.50-8  
 Front Left Side: Milas 6 mm Rear Left Side: Milas 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	726.00	616.80	109.20	15.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	1,035.00	2,875.00	73.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,636.00</b>	<b>1,651.80</b>	<b>2,984.20</b>	<b>64.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	4,636.00	1,300.00	3,336.00	71.96
<b>+ GST 9.00/9.00% (S\$)</b>	417.24	117.00	300.24	71.96
<b>Nett Amount (S\$)</b>	<b>5,053.24</b>	<b>1,417.00</b>	<b>3,636.24</b>	<b>71.96</b>
<b>+ Loss of Use (4.0 x S\$20.00/day) (S\$)</b>		80.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>1,499.18</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,450.00</b>		

**INSPECTION**

Date of Assignment: 16/08/2024  
 Date Inspected: 16/08/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)  
 Industrial City  
 Singapore 533758  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BEADING BODY SHIELD	Scratched	388.00 F	*388.00 FL
2	1		*HANDLE GRIP	Torn	78.00 F	*78.00 FL
3	1		*KICK STARTER	Cut	155.00 F	*155.00 FL
4	2		*PLATE NUMBER FRONT (STRAIGHT)	Not Necessary	44.00 F	*- FL
5	1		*PLATE NUMBER REAR (6.5 INCH X9 INCH)	Necessary	30.00 FS	*30.00 FS
6	1		*RUBBER KICK STARTER	Cut	31.00 F	*31.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	726.00	682.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	65.20
Total Parts (S\$)	726.00	616.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	BODY SPRAY PAINT	New	2,500.00	500.00
2	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	1,360.00	500.00
3	TRANSPORT CHARGES	New	50.00	35.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,910.00</b>	<b>1,035.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >