10/9/24, 11:10 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24080250/EQP3E2

Date: 09/10/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MZC03185

Claimant Vehicle SUG016P CR 17407M

No: SH6916B Insured Vehicle No: GBJ7407M

Date of Loss: 15/08/2024 Nature of Claim: TP Claim No: M2404624

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH6916B

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU298716

Reg. Date: 06/08/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164995

Colour: Blue Odometer: 760584 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
	1,853.12	1,031.12	822.00	44.36
	12.00	12.00	0.00	0.00
	820.00	680.00	140.00	17.07
	0.00	0.00	0.00	
	0.00	0.00	0.00	
otal (S\$)	2,685.12	1,723.12	962.00	35.83
en) (S\$)		1,400.00		
(S\$)	2,685.12	1,400.00	1,285.12	47.86
0% (S\$)	241.66	126.00	115.66	47.86
unt (S\$)	2,926.78	1,526.00	1,400.78	47.86
((S\$) (S\$) (S\$)	1,853.12 12.00 820.00 0.00 0.00 0.00 etal (\$\$) 2,685.12 en) (\$\$) (\$\$) 2,685.12 241.66	1,853.12 1,031.12 12.00 12.00 820.00 680.00 0.00 0.00 0.00 0.00 tal (\$\$) 2,685.12 1,723.12 en) (\$\$) 2,685.12 1,400.00 (\$\$) 2,685.12 1,400.00 0% (\$\$) 241.66 126.00	1,853.12 1,031.12 822.00 12.00 12.00 0.00 820.00 680.00 140.00 0.00 0.00 0.00 0.00 0.00 0.00 tal (\$\$) 2,685.12 1,723.12 962.00 en) (\$\$) 1,400.00 (\$\$) 2,685.12 1,400.00 1,285.12 0% (\$\$) 241.66 126.00 115.66

INSPECTION

Date of Assignment: 16/08/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 16/08/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/9/24, 11:10 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Oct 2024)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6916B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars		Condition	Repairer's	Amount
1	1		*REAR BUMPER		Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CTR MOULD	ING	Broken	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCE	MENT	Not Necessary	394.80 FL	*-FL
4	2		*REAR BUMPER REINFORCE	MENT BRKT RH / LH	Not Necessary	276.20 FL	*- FL
5	1		*REAR BUMPER LWR MOULD	ING	Not Necessary	155.00 FL	*-FL
6	10		*REAR BUMPER CLIPS		Necessary	22.00 FL	*22.00 FL
7	1		*REVERSE SENSOR		Cut	180.00 F	*180.00 F
8	1		*REAR BUMPER MAT		Necessary	50.00 F	*50.00 F
9	1		*REAR BUMPER FOGLAMP		Not Necessary	201.50 FL	*-FL
10	1		*REAR NO.PLATE WITH TRIM	COVER	Broken	55.00 F	*55.00 F
F=Fra	anchise	part. L=ListIt	emDisc.		-		
					Sub Total (S\$)	2,245.15	1,217.65
				- List Item Discount on L Items	20.00/20.00% (S\$)	392.03	186.53
					Total Parts (S\$)	1,853.12	1,031.12
					_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount			
Mis	Miscellaneous Items							
1	1	OD/TP Case (Insurer)		12.00	12.00			
			Sub Total (S\$)	12.00	12.00			

Recommended Labour

	Lab.Type	Repairer's	Amount
ΓING	New	400.00	380.00
TING	New	300.00	280.00
E SENSOR	New	120.00	20.00
	Gross Labour Cost (S\$)	820.00	680.00
ı	TING ITING E SENSOR	TING New ITING New E SENSOR New	TING New 400.00 ITING New 300.00 E SENSOR New 120.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.