

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24080253/RUA3Q2**Date:** 21/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SNK3677D **Insured Vehicle No :** GBJ2646Y
Date of Loss: 15/08/2024 Nature of Claim: TP Claim No: MFL2024D0009638

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNK3677D**
Make & Model: BMW 216I, 1.5 ACTIVE TOURER (A) Engine No: 38156251B38A15A
Reg. Date: 27/01/2021 (Man. Year: 2020) Chassis No: WBA2X920107H34174
Colour: Grey Odometer: 56945 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R19 Rear Tyre Size: 235/40 R19
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,220.40	2,680.85	2,539.55	48.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	2,500.00	2,430.00	49.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,150.40	5,180.85	4,969.55	48.96
+ GST 9.00/9.00% (S\$)	913.54	466.28	447.26	48.96
Nett Amount (S\$)	11,063.94	5,647.13	5,416.81	48.96
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,024.38		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 19/08/2024
Date Inspected: 19/08/2024 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2024)
Parts:	143	BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK3677D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	987.80 F	*- F
2	1		*KIA ADD ONS	Not Necessary	73.95 F	*- F
3	1		*SUPPORT FOGLIGHT LH	Not Necessary	165.15 F	*- F
4	1		*BUMPER MOUNT TOP LH	Not Necessary	57.55 F	*- F
5	1		*BUMPER MOUNT BOTTOM LH	Not Necessary	15.85 F	*- F
6	1		*MOUNT FOR PDC LH	Necessary	23.65 F	*23.65 F
7	1		*MOUNT FOR PDC RH	Not Necessary	23.65 F	*- F
8	4		*CLIP RETAINER	Necessary	19.00 F	*19.00 F
9	1		*FRONT GRILLE LH	Not Necessary	125.55 F	*- F
10	1		*FRONT GRILLE RH	Not Necessary	167.45 F	*- F
11	1		*GRILLE LOWER BUMPER	Not Necessary	170.55 F	*- F
12	1		*GRID LATERAL LH	Not Necessary	102.35 F	*- F
13	1		*FINISHER LH	Scratched	55.45 F	*55.45 F
14	1		*MOULDING LH	Not Necessary	62.55 F	*- F
15	1		*TRIM STRIP CENTER	Not Necessary	55.05 F	*- F
16	3		*ADHESIVE PAD	Not Necessary	5.40 F	*- F
17	1		*FRONT REINFORCEMENT	Not Necessary	420.15 F	*- F
18	1		*BMW LOGO	Not Necessary	76.55 F	*- F
19	1		*HEADLIGHT LH	Broken	2,503.55 F	*2,503.55 F
20	1		*KIT MOUNT FOR HEADLIGHT	Necessary	59.20 F	*59.20 F
21	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
Total Parts (S\$)					5,220.40	2,680.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
2	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	500.00	500.00
3	TO REMOVE /REPLACE FRONT BUMPER AND ALL RELATED DAMAGED BODY PARTS TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,700.00	850.00
4	TO RESPRAY FRONT BUMPER	New	1,980.00	1,000.00
5	TO TRANSFER THE FRONT PARKING SENSOR	New	500.00	0.00
Gross Labour Cost (\$\$)			4,930.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >