

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080254/KUA3Q2**Date:** 05/12/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070151803
Claimant Vehicle No :	SLC3016C	Insured Vehicle No :	SMV9033B
Date of Loss:	15/08/2024	Nature of Claim:	TP
		Claim No:	3267812115SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3016C	Engine No:	8ARW222442
Make & Model:	LEXUS NX200T, 2.0 F SPORT (A)	Chassis No:	JTJBABZ802065668
Reg. Date:	10/05/2016 (Man. Year: 2016)	Odometer:	128138 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,925.75	1,798.42	1,127.33	38.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	1,060.00	420.00	28.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,405.75	2,858.42	1,547.33	35.12
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	4,405.75	2,250.00	2,155.75	48.93
+ GST 9.00/9.00% (S\$)	396.52	202.50	194.02	48.93
Nett Amount (S\$)	4,802.27	2,452.50	2,349.77	48.93
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,774.68		

INSPECTION

Date of Assignment:	28/08/2024	
Date Inspected:	28/08/2024	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LH SIDE RETAINER	Distorted	137.00 FL	*137.00 FL
2	1		*REAR BUMPER TOP	Buckled	955.90 FL	*955.90 FL
3	1		*REAR BUMPER LOWER	Cut	638.40 FL	*638.40 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	1,222.50 FL	*- FL
5	1		*REAR BUMPER LH REFLECTOR	Serviceable	90.30 FL	*- FL
6	1		*REAR LH REVERSE SENSOR	Scratched	380.60 FL	*380.60 FL
7	1		*REAR LH WHEEL ARC GARNISH	Serviceable	190.30 FL	*- FL
8	6		*REAR BUMPER CLIP	Necessary	27.00 FL	*27.00 FL
9	1		*TAILGATE EMBLEM LEXUS	Necessary	121.00 FL	*121.00 FL
10	1		*TAILGATE EMBLEM NX200T	Necessary	138.00 FL	*138.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,901.00	2,397.90
- List Item Discount on L Items 25.00/25.00% (\$)	975.25	599.48
Total Parts (\$)	2,925.75	1,798.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER ASSY TO KNOCKING & REPAIR REAR LH FENDER ,REAR END PANEL & REALIGN THE SAME	New	600.00	400.00
2	PUTTY & RESPRAY ON REAR BUMPER TAILGATE REINFORCEMENT REAR LH FENDER REAR PANEL	New	800.00	600.00
3	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	80.00	60.00
Gross Labour Cost (\$\$)			1,480.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >