

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080255/APA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000122
Claimant Vehicle No :	GBK8010L	Insured Vehicle No :	GBJ4920S
Date of Loss:	03/08/2024	Nature of Claim:	TP
		Claim No:	1987277839SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK8010L		
Make & Model:	TOYOTA HILUX, 2.4 D G DOUBLE CAB (A)	Engine No:	HIDDEN
Reg. Date:	01/12/2020 (Man. Year: 2020)	Chassis No:	AHTBB3CD101761961
Colour:	Black/White	Odometer:	29314 km
Engine Capacity:	2393 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/60 R18	Rear Tyre Size:	265/60 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,263.30	9,206.45	12,056.85	56.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,170.00	1,430.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,863.30	10,376.45	13,486.85	56.52
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	23,863.30	8,300.00	15,563.30	65.22
+ GST 9.00/9.00% (S\$)	2,147.70	747.00	1,400.70	65.22
Nett Amount (S\$)	26,011.00	9,047.00	16,964.00	65.22
+ Car Rental (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		9,558.00		
Global Sum Settlement (S\$)		9,550.00		

INSPECTION

Date of Assignment:	14/08/2024		
Date Inspected:	14/08/2024	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEADLAMP	Cracked	7,505.40 FL	*6,120.00 FL
2	2		*SETS HEADLAMPS BRACKETS	Not Necessary	197.20 FL	*- FL
3	1		*FRONT GRILLE	Cracked	2,430.30 FL	*1,910.00 FL
4	1		*FRONT BUMPER	Deformed	924.10 FL	*924.10 FL
5	2		*FRONT BUMPER BRACKETS	Not Necessary	197.00 FL	*- FL
6	2		*FRONT BUMPER WASHER COVER	Not Necessary	130.40 FL	*- FL
7	2		*FRONT BUMPER WASHER NOZZLE	Not Necessary	397.20 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	337.80 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	897.50 FL	*658.00 FL
10	1		*FRONT BUMPER REINFORCEMENT COVER	Deformed	225.80 FL	*225.80 FL
11	1		*FRONT BUMPER TOP SUPPORT BEAM	Deformed	285.60 FL	*285.60 FL
12	1		*FRONT BUMPER LOWER GRILLE	Deformed	398.50 FL	*398.50 FL
13	1		*FRONT BUMPER LOWER COVER	Deformed	145.80 FL	*145.80 FL
14	1		*FRONT BUMPER FOG LAMP COVER	O/S Cracked	315.60 FL	*157.80 FL
15	1		*FRONT BUMPER FOG LAMP	O/S Cracked	797.00 FL	*398.50 FL
16	1		*FRONT RADIATOR BRACE PANEL	Bent	198.70 FL	*198.70 FL
17	1		*FRONT RADIATOR AIR GUIDES	O/S Deformed	291.60 FL	*145.80 FL
18	1		*FRONT WASHER TANK	Not Necessary	285.90 FL	*- FL
19	1		*FRONT RADIATOR EXPANSION TANK	Not Necessary	298.50 FL	*- FL
20	1		*FRONT BONNET	Not Necessary	3,458.90 FL	*- FL
21	1		*FRONT BONNET GARNISH	Repair	285.30 FL	*- FL
22	1		*FRONT BONNET INNER LOCK	Not Necessary	235.90 FL	*- FL
23	1		*FRONT SUPPORT PANEL	Repair	1,790.00 FL	*- FL
24	1		*TURBO INTERCOOLER	Not Necessary	2,245.60 FL	*- FL
25	2		*RADIATOR AIR GUIDES	Repeated	197.20 FL	*- FL
26	2		*AIR CON PIPES	Not Necessary	491.60 FL	*- FL
27	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET FRONT BONNET STICKER	Not Necessary	950.00 FS	*- FS
30	1		*SET FRONT BUMPER STICKER	Necessary	850.00 FS	*300.00 FS
31	1		*SET FRONT GRILLE STICKER	Necessary	450.00 FS	*180.00 FS
32	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
33	1		*FRONT GRILLE LOGO	Not Necessary	120.00 FS	*- FS
34	2		*SET HEADLAMP CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,504.40	12,098.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,241.10	2,892.15
Total Parts (\$\$)	21,263.30	9,206.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	600.00
2	SPRAY PAINTING	New	1,200.00	500.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	80.00	30.00
4	ANTI RUST	New	120.00	40.00
Gross Labour Cost (\$\$)			2,600.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >