

Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Invoice

Customer: Pan Lei

Date:

12.05.2024

C/o:

7 Sin Ming Industrial Estate Sector C #01-94

Singapore 575642

Invoice No: NS-2024-088

	Description					
Vehicle No:	SKR2346P					
Make & Model:	Audi A6 2.0 TFSI (A)					
Our reference:	AAS/2024/088					
Services rendered	Services rendered for appraiser / inspection report					
Survey Fee						
Photographs						
Transport Fees						
Re-inspection Fees						
SGD Dollar : Seven l	nundred twenty seven dollar only	Total:	SGD \$ 727.00			
,						

Notes:

All cheques payment should be crossed and made payment to "Absolute Appraisal Services Pte Ltd"

Please indicate our "Invoice No." on the reverse side of the cheque.

Please do not hesitate to contact us should you have any enquires.

Absolute Apprical Services Pte Ltd



Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle Inspection Report

To: Pan Lei Date of report: 12.05.2024 C/o: 7 Sin Ming Industrial Estate Sector C #01-94 Date of request: 24.04.2024

Singapore 575642 Date of inspection: 24.04.2024
Date of accident: 20.04.2024

Report No: AAS/2024/088 Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no: SKR2346P Odometer: 175226 km Make/Model: Audi A6 2.0 TFSI (A) Engine Capacity: 1984 cc
Year of registration: 2014/15 Engine no: CDN412251

Colour: Metallic Black Chassis no: WAUZZZ4G0EN170424

Condition of tires:

Front Right: 6mm Front Left: 6mm Michelin Michelin Make: Make: Rear Right: 6mm 6mm Rear Left: Michelin Make: Michelin Make:

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conduct at M/s. MJE Motor Pte Ltd

7 Sin Ming Industrial Estate Sector C #01-94

Singapore 575642

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 11,124.20

Revised estimate: \$ 7,995.50

Recommended reserve: \$ 6,400.00 (Lump sum)

Estimated normal duration of repairs \$5 Working days



Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SKR2346P Report No: AAS/2024/088

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The boot lid, rear bumper, rear end panel, exhaust muffler LH, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s MJE Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$7,995.50

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$6,400.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 5 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 67 photographs.

Your Faithfully Absolute Appraisal Services Pte Ltd



Nicky Seah Automobile Appraiser MSAAA / MSMCTA



Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Vehicle No: SKR2346P						Report No: AAS/2024/088				
App	raisement Schedule									
C /3.T		Qty	C I'ti'			Repairer's Est		Revised Est		
	S/N Parts Description		Condition				117.00	, Ke	117.00	
1	Boot lid emblem	1	Necessary			\$				
2	Boot lid nameplate 'A6'	1	Necessary			\$	90.00	\$	90.00	
3	Boot lid nameplate 'TFSI'	1	Necessary			\$	83.00	\$	83.00	
4	Boot lid sensor module	1	Cracked			\$	485.00	\$	485.00	
5	Boot lid sensor harness	1	Serviceable			\$	248.00		5=00	
6	Tail lamp LH/RH	2	Serviceable	\$	1,019.00	\$	2,038.00		960	
7	Rear bumper	1	Dented			\$	2,996.00	\$	2,996.00	
8	Rear bumper lower	1	Dented			\$	249.00	\$	249.00	
9	Rear bumper tow cap	1	Serviceable			\$	33.00		120	
10	Rear bumper reinforcement	1	Dented			\$	1,002.00	\$	1,002.00	
11	Rear bumper bracket LH/RH	2	Serviceable	\$	116.00	\$	232.00		: =)	
12	Rear bumper lower bracket	2	Serviceable	\$	46.00	\$	92.00		187	
13	Rear bumper centre guide	1	Cracked			\$	175.00	\$	175.00	
14	Rear parking aid	2	Malfunctioned	\$	233.00	\$	466.00	\$	466.00	
15	Rear parking aid seal ring	4	Necessary	\$	3.50	\$	14.00	\$	14.00	
16	Exhaust muffler LH	1	Dented/Bent			\$	1,570.00	\$	1,570.00	
17	Exhaust muffler clamp	1	Necessary			\$	48.00	\$	48.00	
18	Rear end panel		Dented/Repair				125		=	
19	Boot lid		Chipped/Repair				7.E.		i=1	
			11 / 1							
				Total:		\$	9,938.00	\$	7,295.00	
				-10%		\$	993.80	\$	729.50	
						\$	8,944.20	\$	6,565.50	
				List total:		\$	8,944.20	\$	6,565.50	



Loss Adjusters & Motor Appraisers

160 Sin Ming Drive, #05-11 Sin Ming AutoCity (S) 575 722 Email: absolute.app.svcs@gmail.com Mobile: 9688 0413

Veh	icle No: SKR2346P	Rej	ort No: AAS	/2024/	088	
S/N Labour Description			Repairer's Est		Revised Est	
1	Check lightings & wirings.	\$	50.00	\$	30.00	
2	Replace & transfer reverse sensor.	\$	80.00	\$	50.00	
3	Anti rust treatment on rear affected panels.	\$	50.00	\$	30.00	
4	Replace LH exhaust muffler.	\$	200.00	\$	120.00	
5	To conduct panel beating, welding, straightening of damaged panels, renew rear damaged parts, realign affected area.	\$	800.00	\$	500.00	
6	Spray painting on rear replacement & affected parts.	\$	1,000.00	\$	700.00	
	Labour Total:	\$	2,180.00	\$	1,430.00	
	Grand Total:	\$	11,124.20	\$	7,995.50	

The final adjusted lump sum amount is \$

\$6,400.00

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

67 Photographs were taken at the time of inspection.







































































