

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKR 2346P

	REPLACEMENT OF PARTS			
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BOOT LID EMBLEM	NOT CHANGED	\$117.00	\$0.00
1	BOOT LID NAMEPLATE 'A'	NOT CHANGED	\$90.00	\$0.00
1	BOOT LID NAMEPLATE "TFSI"	NOT CHANGED	\$83.00	\$0.00
1	BOOT LID SENSOR MODULE	REPLACED	\$485.00	\$485.00
1	BOOT LID SENSOR HARNESS	SERVICEABLE	\$248.00	\$0.00
2	TAIL LAMP LH / RH @\$1019.00	SERVICEABLE	\$2,038.00	\$0.00
1	REAR BUMPER	REPLACED	\$2,996.00	\$2,941.60
1	REAR BUMPER LOWER	REPLACED	\$249.00	\$249.00
1	REAR BUMPER TOW CAP	SERVICEABLE	\$33.00	\$0.00
1	REAR BUMPER REINFORCEMENT	REPLACED	\$1,002.00	\$1,002.00
2	REAR BUMPER BRACKET LH / RH @\$116.00	SERVICEABLE	\$232.00	\$0.00
2	REAR BUMPER LOWER BRACKET @\$46.00	SERVICEABLE	\$92.00	\$0.00
1	REAR BUMPER CENTRE GUIDE	REPLACED	\$175.00	\$175.00
2	REAR PARKING AID @\$233.00	REPLACED	\$466.00	\$466.00
4	REAR PARKING AID SEAL RING @\$3.50	REPLACED	\$14.00	\$14.00
1	EXHAUST MUFFLER CLAMP	NOT CHANGED	\$48.00	\$0.00
1	REAR END PANEL (NPA)	REPAIRED SEE LABOUR	\$0.00	\$0.00
1	BOOT LID (NPA)	REPAIRED SEE LABOUR	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$836.80)	(\$533.26)
			\$7,531.20	\$4,799.34

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	EXHAUST MUFFLER LH (SN) (LOCAL REPAIR)	REPLACED	\$1,413.00	\$250.00
		\$1,413.00	\$250.00	

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK LIGHTING & WIRINGS		\$50.00	\$30.00
	REPLACE & TRANSFER REVERSE SENSOR		\$80.00	\$50.00
	ANTI RUST TREATMENT ON REAR AFFECTED PANELS	NOT NECESSARY	\$50.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
REPLACE LH EXHAUST MUFFLER		\$200.00	\$80.00	
TO CONDUCT PANEL BEATING, WELDING, STRAIGHTENING OF DAMAGED PANELS, RENEW REAR DAMAGED PARTS, REALIGN AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND BOOT LID		\$800.00	\$400.00	
SPRAY PAINTING ON REAR REPLACEMENT & AFFECTED PARTS		\$1,000.00	\$500.00	
		\$2,180.00	\$1,060.00	
GRAND TOTAL		\$11,124.20	\$6,109.34	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,850.00	
Report Ref No: CS/SMO24080266/Kqp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.