



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNG 269P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP - LH	CRACKED	\$4,495.00	\$3,677.73
1	FRONT BUMPER	CUT/TORN	\$2,198.00	\$1,723.81
1	SET FRONT BUMPER CLIP	NECESSARY	\$80.00	\$60.00
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	\$165.00	\$0.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$596.00	\$0.00
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	\$75.00	\$75.00
1	FRONT BUMPER SIDE GRILLE N/S	CUT	\$155.00	\$86.00
1	FRONT BUMPER CHROME MOULDING	SCRATCHED	\$125.00	\$72.00
2	FRONT BUMPER SIDE PDC SENSORS	SERVICEABLE	\$710.00	\$0.00
1	FRONT FENDER - LH	BADLY DENTED	\$1,550.00	\$1,162.73
1	FRONT FENDER INNER SHIELD	TWISTED	\$175.00	\$175.00
1	FRONT WHEEL RIM - LH	TO REPAIR SEE LABOUR	\$2,880.00	\$0.00
1	FRONT WHEEL HUB WITH BEARING	NOT NECESSARY	\$587.54	\$0.00
1	FRONT SHOCK ABSORBER	NOT NECESSARY	\$727.78	\$0.00
1	FRONT KNUCKLE ARM	NOT NECESSARY	\$1,027.09	\$0.00
1	FRONT LOWER ARM	NOT NECESSARY	\$1,038.00	\$0.00
1	FRONT TOP ARM	NOT NECESSARY	\$479.20	\$0.00
1	FRONT CONTROL ARM	NOT NECESSARY	\$437.00	\$0.00
1	STABILIZER BAR LINK	NOT NECESSARY	\$97.10	\$0.00
	LESS 5.00 / 10.00% DISCOUNT		(\$879.89)	(\$703.23)
			\$16,717.82	\$6,329.04
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT TYRE (SN)	NOT NECESSARY	\$650.00	\$0.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	\$60.00	\$30.00
			\$710.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING		\$80.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT FRONT SENSOR	NOT NECESSARY	\$180.00	\$30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE		\$350.00	\$0.00
	TO CONDUCT WHEEL ALIGNMENT		\$180.00	\$60.00
	TO APPLY UNDERCOATING		\$150.00	\$30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT WHEEL RIM - LH		\$1,500.00	\$300.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	NOT NECESSARY	\$1,400.00	\$400.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR		\$600.00	\$0.00
			\$4,440.00	\$840.00
GRAND TOTAL			\$21,867.82	\$7,199.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$5,700.00
Report Ref No: CS/INC24060110/Uvh3e2				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser