

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS MS FIRST CAPITAL INSURANCE LTD Ref: CS/FCI24080272/Ugh3 16 RAFFLES QUAY Date: 03/09/2024 #42-01 HONG LEONG BUILDING SINGAPORE 048581 Code: FCI2 1. **Policy Particulars :- THIRD PARTY CLAIM** Insured Veh. SHC 1722H Veh. Inspected **SLB 2695D** Policy No. D-24101861MFCT Coverage Claim No. D24007239MFCT **Excess** \$0.00 **Assign From** HARMINDER KAUR **Assign Date** 19/08/2024 2. **Vehicle Details** C.C Make & Model 1496 HONDA VEZEL 1.5X (A) Engine No. L15B4029795 Year of Reg. 31/03/2016 Chassis No. **SILVER** RU11109791 Colour Odometer 396685 KM IN ORDER Steering **Brakes** IN ORDER GOOD General Modification(s) RIMS: SPORTS RIM **Conditions of Tyres** 3. Size Make Balance (mm) 215/60R16 **FIRENZA R/H Front Tyre** 6 L/H Front Tyre 215/60R16 **FIRENZA** 6 R/H Rear Tyre 215/60R16 **FIRENZA** 6 L/H Rear Tyre 215/60R16 **FIRENZA** 6 **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. **General Information** Inspection Date **Accident Date** 19/08/2024 16/08/2024

Accident Date 16/08/2024 Inspection Date 19/08/2024

Survey held at FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY

5a. Remarks

SINGAPORE 417883

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.

B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days