

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080275/AMA3Q2
Date: 05/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0007785_01
Claimant Vehicle No : SLG381X Insured Vehicle No : SKT7042Y
Date of Loss: 15/08/2024 Nature of Claim: TP Claim No: MFL2024D0009622

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG381X
Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A) Engine No: CAXF55661
Reg. Date: 19/09/2016 (Man. Year: 2015) Chassis No: WVWZZZ16ZFM046549
Colour: Blue Odometer: 159707 km
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,978.21	7,962.92	6,015.29	43.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,930.00	1,400.00	42.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,308.21	9,892.92	7,415.29	42.84
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	17,308.21	7,900.00	9,408.21	54.36
+ GST 9.00/9.00% (S\$)	1,557.74	711.00	846.74	54.36
Nett Amount (S\$)	18,865.95	8,611.00	10,254.95	54.36
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,998.25		
Global Sum Settlement (S\$)		8,990.00		

INSPECTION

Date of Assignment: 19/08/2024
Date Inspected: 19/08/2024 Inspected At: Twincar Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVEUNE 2 #01-17
Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG381X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH ABS SENSOR	Not Necessary	169.69 FL	*- FL
2	1		*REAR RH CONTROL ARM	Bent	688.91 FL	*688.91 FL
3	1		*REAR RH DOOR	Repair	1,997.60 FL	*- FL
4	1		*REAR RH DOOR MECHANISM LOCK	Not Necessary	900.91 FL	*- FL
5	1		*REAR RH DOOR WEATHERSTRIP	Not Necessary	333.21 FL	*- FL
6	1		*REAR RH FENDER	Dented	1,999.69 FL	*1,758.00 FL
7	1		*REAR RH FENDER INNER PANEL	Repair	505.00 FL	*- FL
8	1		*REAR RH FENDER INNER SHIELD	Torn	333.96 FL	*333.96 FL
9	1		*REAR RH KNUCKLE ARM	Broken	1,314.56 FL	*659.00 FL
10	1		*REAR RH KNUCKLE ARM BEARING	Damaged	797.79 FL	*627.00 FL
11	1		*REAR RH LOWER ARM	Bent	700.81 FL	*700.81 FL
12	1		*REAR RH SHOCK ABSORBER (BC RACING)	Bent	600.88 FL	*600.88 FL
13	1		*REAR RH SHOCK ABSORBER TOP MOUNTING	Not Necessary	333.21 FL	*- FL
14	1		*REAR RH STABILIZER LINK	Bent	180.11 FL	*180.11 FL
15	1		*REAR RH TRAILING ARM	Bent	796.00 FL	*520.00 FL
16	1		*REAR RH UPPER ARM	Bent	600.33 FL	*600.33 FL
17	1		*ROCKER GARNISH RH	Cut	900.91 FL	*900.91 FL
18	1		*REAR RH 225/40R18 TYRE	Cut	800.00 FS	*200.00 FS
19	1		*SET REAR RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*REAR RH SPORT RIM	Cut	1,080.00 FS	*800.00 FS
21	1		*REAR WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
23	1		*SET ROCKER GARNISH RH CLIPS	Necessary	50.00 FS	*30.00 FS
					Sub Total (\$\$)	15,293.57 8,719.91
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,315.36 756.99
					Total Parts (\$\$)	13,978.21 7,962.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REINSTALL WINDSCREEN (REAR)	New	150.00	120.00
2	TO REMOVE CHARGE REAR SUSPENSION PARTS AXLE CARRIAGE ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM, WHEEL BEARING ,BEARIG HUB AND ETC	New	400.00	250.00
3	TO ROAD TEST DRIVING CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
4	TO REMOVE REINSTALL PETROL TANK (TO FR)	New	80.00	60.00
5	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
6	TO TRANSFER DOOR GLASS ,RERULATOR GEAR,MOTOR ,RAILING CHANNEL TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	0.00
7	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	600.00
8	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
9	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			3,330.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >