

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLG381X Yr Regn: 2016 / Sept.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Jetta C.D. 1390
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 15907 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVW 22216 ZFM 046549
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/40 R18
 R: 225/40 R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>06</u> mm	R/Bal.	<u>06</u> mm
L/Bal.	<u>06</u> mm	L/Bal.	<u>06</u> mm
D.O.A.		D.O.I.	<u>19/08/24.</u>

Survey held at Twinkl.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP III</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes C ✓</u>
	<u>1st Survey : No C)</u>
	<u>MV : 351K</u>
	<u>PV : 24.3K</u>
	<u>Nett : 10.7K</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)

Survey Fee: _____
 Transportation: _____
☐ : 3 + RS. \$1
☐ : Photos
☐ : Others

Report Format: _____

Report Form: _____

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MUHAMMAD FARHAN BIN SAIN
159 YUNG PING RD #02-09
SINGAPORE 610159

Contact : 91692051

TAX INVOICE

Repair Code : CLM16395

Date in : 16/08/2024

Vehicle Num. : SLG381X

Model : VOLKSWAGEN JETTA 1.4 TSI 1633G5 HID SR NAV

Chassis/Eng# : WVVZZZ16ZFM046549/CAXF55661

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR RH ABS SENSOR <i>new</i>	1	169.69	+ 169.69
REAR RH CONTROL ARM <i>Bent</i>	1	688.91	- 688.91
REAR RH DOOR <i>Repair</i>	1	1997.60	+ 1,997.60
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	900.91	+ 900.91
REAR RH DOOR WEATHER STRIP <i>new</i>	1	333.21	+ 333.21
REAR RH FENDER <i>Dented</i>	1	1999.69	✓ 1,999.69
REAR RH FENDER INNER PANEL <i>Repair</i>	1	505.00	+ 505.00
REAR RH FENDER INNER SHIELD <i>torn</i>	1	333.96	✓ 333.96
REAR RH KNUCKLE ARM <i>cracked Broken</i>	1	1314.56	✓ 1,314.56
REAR RH KNUCKLE ARM BEARING <i>2nd</i>	1	797.79	✓ 797.79
REAR RH LOWER ARM <i>Bent</i>	1	700.81	✓ 700.81
REAR RH SHOCK ABSORBER (BC RACING) <i>Bent</i>	1	600.88	✓ 600.88
REAR RH SHOCK ABSORBER TOP MOUNTING <i>new</i>	1	333.21	+ 333.21
REAR RH STABILIZER LINK <i>Bent</i>	1	180.11	✓ 180.11
REAR RH TRAILING ARM <i>Bent</i>	1	796.00	✓ 796.00
REAR RH UPPER ARM <i>Bent</i>	1	600.33	✓ 600.33
ROCKER GARNISH RH <i>lt</i>	1	900.91	✓ 900.91

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

MUHAMMAD FARHAN BIN SAIN
 159 YUNG PING RD #02-09
 SINGAPORE 610159

Contact : 91692051

TAX INVOICE

Repair Code : CLM16395

Date in : 16/08/2024

Vehicle Num. : SLG381X

Model : VOLKSWAGEN JETTA 1.4 TSI 1633G5 HID SR NAV

Chassis/Eng# : WVVZZZ16ZFM046549/CAXF55661

Subtotal before discount		13,153.57
Percentage discount	10%	1,315.36
Sub-total 1		11,838.21
REAR RH 225/40R18 TYRE <i>cut</i>	1	800.00 <i>200 800.00</i>
REAR RH FENDER INNER SHIELD CLIPS - SET <i>rw</i>	1	50.00 <i>50 50.00</i>
REAR RH SPORT RIM <i>lt</i>	1	1080.00 <i>800 1,080.00</i>
REAR WINDSCREEN SEAL <i>3</i>	1	80.00 <i>40 80.00</i>
REAR WINDSCREEN SEALANT <i>3</i>	1	80.00 <i>30 80.00</i>
ROCKER GARNISH RH CLIPS - SET <i>rw</i>	1	50.00 <i>30 50.00</i>
Subtotal before discount		2,140.00
Percentage discount	0%	0.00
Sub-total 2		2,140.00
Parts-total		13,978.21

LABOUR

To remove, reinstall windscreen (REAR)

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

120 150.00
250 400.00
80 100.00
60 80.00
60 100.00
X 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MUHAMMAD FARHAN BIN SAIN
159 YUNG PING RD #02-09
SINGAPORE 610159

Contact : 91692051

TAX INVOICE

Repair Code : CLM16395

Date in : 16/08/2024

Vehicle Num. : SLG381X

Model : VOLKSWAGEN JETTA 1.4 TSI 1633G5 HID SR NAV

Chassis/Eng# : WVVZZZ16ZFM046549/CAXF55661

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,100.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,200.00

To apply anti-rust chemical on repaired and replaced panel.

120.00

Labour Total

3,330.00

Parts & Labour Total

17,308.21

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lj
1/s 19/08/24
Ob Rys