



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2500390

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 16/01/2025
Reference CD/CTI24080276/Tpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 5890A
Insured Veh. SKZ 2740S
Claim No. SNM24D203618
Policy No. DMPCSNW00002992407
Accident Date 21/06/2024
Inspection Date 16/08/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24080276/Tpa3q2
3 ANSON ROAD #16-00	Date:	16/01/2025
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SKZ 2740S	Veh. Inspected	SMB 5890A
Policy No.	-	Coverage	0
Claim No.	SNM24D203618	Excess	\$0.00
Assign From	JENNY LEW	Assign Date	16/08/2024

2. Vehicle Details

Make & Model	MAN A95	C.C	10518
Engine No.	50340851464066	Year of Reg.	12/10/2015
Chassis No.	WMAA95ZZ8F7002865	Colour	MULTI
Odometer	498168 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	275/70 R22.5	FALKEN	8
L/H Front Tyre	275/70 R22.5	FALKEN	8
R/H Rear Tyre	275/70 R22.5 (D)	FALKEN	8/8
L/H Rear Tyre	275/70 R22.5 (D)	FALKEN	8/8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2024	Inspection Date	16/08/2024
Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMB 5890A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER CORNER:R/H, FOR ADL E500 DD BUS	TO REPAIR SEE LABOUR	\$1,181.40	\$0.00
1	DOME, FRONT PANEL: FOR ADL E500 DD BUS	TO REPAIR SEE LABOUR	\$7,732.80	\$0.00
			\$8,914.20	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPAIR RH PORTION. INCLUSIVE OF THE REPAIR OF BUMPER CORNER R/H FOR ADL E500 DD BUS AND DOEM FRONT PANEL FOR ADL E500 DD BUS.		\$1,060.00	\$530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$878.00	\$708.00
			\$1,938.00	\$1,238.00

GRAND TOTAL			\$10,852.20	\$1,238.00
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF REPAIRS			\$1,238.00
--	------------------------------------	--	--	-------------------

Report Ref No: CD/CTI24080276/Tpa3q2

MTH

MOHAMAD TAUFIKH


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMB 5890A



PHOTOGRAPHS FOR VEHICLE NO. : SMB 5890A



PHOTOGRAPHS FOR VEHICLE NO. : SMB 5890A

