

ASS. REC. BY: Taujith

REF: CO/CTI 24080276/Tp13

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMB5890A Yr Regn: 2015, 10  
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: MAN A95 c.c. 10518  
 Colour: Mult A/C: Insured / Std / NI / NA  
 Sp. Reading: 498168 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WMAVA 95Z2RF 7002865  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: NI / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 275 70R22.5  
 R: " " (D)  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Falken

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 8/8 mm  
 L/Bal. 8 mm L/Bal. 8/8 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 16/8/24  
 Survey held at SMRT WL

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: Siddi Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or  
O/S Frt  
 The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) \_\_\_\_\_  
 Rep. Format: \_\_\_\_\_  
 Lump Sum / L.B.K. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB5890A
Case Reference Number	BUS/06/24/5028
Registration Date	10/12/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Yang Shuang
Type of Accident	Side Swipe
Accident Date and Time	6/21/2024 3:33 PM
Accident Reported Date and Time	6/24/2024 10:15 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24122129
Special Instruction to ARC,if any	SMB5890A - RIGHT FRONT PORTION SKZ2740S (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	8/16/2024 2:03 PM
Chassis Number	WMAA95ZZ8F7002865
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$1,938.00</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	3.0	2 DAYS
Prepared / Adjusted By	ARC Manager Team	Taufikh
ARC / Surveyor Sign Off Date	16/08/2024 2:04 PM	16/8/24
Signature	✘	✘ <i>taufikh</i>
Remarks		Taufikh 97495749 WP 16/8/24 P/P RESURVEY AFTER REPAIR taufikh@LKKauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,060.00	530
<b>Total Labour</b>	<b>\$1,060.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	708
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$878.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER,CORNER:R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	100.00	\$0.00	Repair	XR
6011049	Body	20594593/2	DOME,FRONT PANEL:FOR ADL E500 DD BUS	1.00	\$7,732.80	100.00	\$0.00	Repair	XR
<b>Total</b>					<b>\$8,914.20</b>		<b>\$0.00</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									