

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080277/UPA3Q2
Date: 09/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SMN2800S Insured Vehicle No : GBM1824R
Date of Loss: 14/08/2024 Nature of Claim: TP Claim No: MFL2024D0009498

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN2800S
Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) Engine No: HR16950429B
Reg. Date: 23/01/2015 (Man. Year: 2014) Chassis No: MNTBBAB17Z0020858
Colour: Black Odometer: 152138 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm
Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,691.75	1,366.50	3,325.25	70.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	640.00	1,340.00	67.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,671.75	2,006.50	4,665.25	69.93
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	6,671.75	1,600.00	5,071.75	76.02
+ GST 9.00/9.00% (S\$)	600.46	144.00	456.46	76.02
Nett Amount (S\$)	7,272.21	1,744.00	5,528.21	76.02
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		2,171.25		

INSPECTION

Date of Assignment: 19/09/2024
Date Inspected: 19/09/2024 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
2008/2010/2012
Singapore 489977
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2024)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN2800S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Serviceable	801.10 FL	*- FL
2	1		*FRONT GRILLE EMBLEM	Not Necessary	72.00 FL	*- FL
3	1		*HEADLAMP LH	Holder Cracked	986.00 FL	*945.00 FL
4	1		*HEADLAMP RH	Serviceable	986.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	636.70 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Torn	245.00 FL	*190.80 FL
7	1		*AIR CON CONDENSER	Not Necessary	1,100.00 FL	*- FL
8	1		*RADIATOR	Not Necessary	1,016.50 FL	*- FL
9	1		*FRONT BUMPER	Dented / Deformed	759.20 FL	*759.20 FL
10	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*20.00 FS
11	1		*FRONT NUMBER PLATE HOLDER	Bent	35.00 FS	*20.00 FS
12	1		*BONNET (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*FRONT FENDER LH (NPA)	Not Necessary	0.00 FS	*- FS
14	1		*FRONT FENDER RH (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*SUPPORT PANEL (NPA)	Repair	0.00 FS	*- FS
					Sub Total (S\$)	
					6,672.50	1,935.00
					- List Item Discount on L Items 30.00/30.00% (S\$)	
					1,980.75	568.50
					Total Parts (S\$)	
					4,691.75	1,366.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	320.00
3	ANTI-RUST COATING	New	100.00	0.00
4	TO SERVICE & TOP-UP AIR-CON GAS	New	180.00	0.00
5	WIRING	New	100.00	20.00
Gross Labour Cost (S\$)			1,980.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >