



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO XE 9131K

| REPLACEMENT OF PARTS | | | | |
|----------------------|-----------------------------------|----------------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | FRONT BUMPER | DENTED | \$3,186.60 | \$2,250.00 |
| 1 | FRONT LH STEP GARNISH (LOWER) | NOT NECESSARY | \$610.20 | \$0.00 |
| 1 | FRONT LH HEAD LAMP | CUT | \$2,818.70 | \$1,750.00 |
| 1 | FRONT LH SIGNAL LAMP | CRACKED | \$810.20 | \$550.00 |
| 1 | FRONT LH STEP GARNISH | NOT NECESSARY | \$821.70 | \$0.00 |
| 1 | FRONT LH STEP GARNISH REFLECTOR | NOT NECESSARY | \$120.00 | \$0.00 |
| 1 | FRONT LH STEP ALUMINIUM (LOWER) | DENTED | \$300.00 | \$250.00 |
| 1 | FRONT LH STEP ALUMINIUM (UPPER) | NOT NECESSARY | \$300.00 | \$0.00 |
| 1 | FRONT BUMPER LH GARNISH STRIP | NOT NECESSARY | \$110.00 | \$0.00 |
| 1 | FRONT LH STEP GARNISH UPPER (NPA) | TO REPAIR SEE LABOUR | \$0.00 | \$0.00 |
| | LESS 25.00% DISCOUNT | | (\$2,269.35) | (\$1,200.00) |
| | | | \$6,808.05 | \$3,600.00 |

| Labour | | | | |
|--------|--|-----------|------------------------|-------------------|
| | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| | TO REMOVE AND REPLACE DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT LH STEP GARNISH UPPER | | \$1,200.00 | \$600.00 |
| | TO SPRAY PAINTING | | \$800.00 | \$600.00 |
| | TO CHECK WIRING | | \$200.00 | \$50.00 |
| | | | \$2,200.00 | \$1,250.00 |

| | | |
|--------------------|-------------------|-------------------|
| GRAND TOTAL | \$9,008.05 | \$4,850.00 |
|--------------------|-------------------|-------------------|

| | | |
|---|--|-------------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | \$3,850.00 |
|---|--|-------------------|

Report Ref No: CS/INC24080278/Tnh3m4

TOTAL FOR SPARE PARTS: \$ 6,808.05 \$ 3,600.00
TOTAL FOR LABOUR : \$ 2,200.00 \$ 1,250.00
TOTAL REPAIR COST: \$ 9,008.05 \$ 4,850.00

MTH

MOHAMAD TAUFIKH



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.