



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:	CS/INC24080278/Tnh3m4	
75 BRAS BASAH ROAD		Date:	20/09/2024	
INCOME CENTRE SINGAPORE 189557		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNG 6516L	Veh. Inspected	XE 9131K	
Policy No.	-	Coverage	0	
Claim No.	MT/1290936-002	Excess	\$0.00	
Assign From	SERENE LIM	Assign Date	19/08/2024	
2. Vehicle Details				
Make & Model	MITSUBISHI FUSO FV70HJD2VDEA	C.C	10677	
Engine No.	470912C0879270	Year of Reg.	15/03/2024	
Chassis No.	FV70HJA30013	Colour	WHITE	
Odometer	22752 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: NIL			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	295/80R22.5	YOKOHAMA	8	
L/H Front Tyre	295/80R22.5	YOKOHAMA	8	
R/H Rear Tyre	295/80R22.5 (D)	YOKOHAMA	8/8	
L/H Rear Tyre	295/80R22.5 (D)	YOKOHAMA	8/8	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2024	Inspection Date	22/08/2024 (14:44)	
Survey held at	160 SIN MING DRIVE #01-01 SINGAPORE 575722 – REPAIRER: RYDER AUTO PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				