ASS. REC. BY: Tayph Tuh3

ASSIGNMENT

From: Date:	Veh No: XE913/K Yr Regn: 2024, 03					
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /					
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or Tipper truck					
To Inspect Vehicle No:	Make: Mitsubish Fuso Fr70 cc 10677					
at Workshop m/s	Colour WWTL A/C: Insured/Std/NI/NA					
of	Sp.Reading 22752 T/Radio: Insured / Std / NI / NA					
insured:	Eng/No:					
Policy No.	C/No: 5470454 30013					
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt					
Sum Insured; Excess:	Steering: Inorder Jammed / Leaked / Burnt or					
(Client's Record)	Brake: Inorder / Jammed / Leakod / Burnt or					
Make of Veh:	Madl: (NIT) S/Rim / STD A/Rim or					
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  N/S O/S	Tyre Size: F: 295 80 (22.5)  R: \( \sigma \)					
Bal. or Market Value:						
IDAC Accident Roort Consistent? : Yes or No	R/Bal. & mm B/Bal &/ &					
GIA / PR Seen: Consistent?: Yes or No	L/Bal. K					
Est Repairs: days Res.: Yes or No	D.O.A. D.O.J. 22 6 24					
Lum Sum: % 3 Val.: Yes or No Survey held at Ruder						
CA I REV I REP. I 24 HRS  Des. of Damages : Fit   Rear   O/S   N/S   U/G   Rooftop or						
Date:Person Contacted: Vehicle: IN / OUT Fut N S						
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.					
Taufikh confirmed COR I/s \$3850 , 3 days.  (red, \$5075.55, 56%)						
	ays Of Repair: 3					
Date/Time, File Return to?	esurvey No. of Trip: Survey Fee:					
	Transportation:					
Add Fee:						
Permist:	: Interview (\$ ) Photos					
Lemip Sam / LB.J. CF	Tech, Invs (\$ ) Others					
· · · · · · · · · · · · · · · · · · ·	: Weel:end (%					
	TOTAL					



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com Tel: 67418277 Fax: 67468277

## **ESTIMATE OF REPAIR**

Veh#

XD9131K

Model:

MITSUBISHI

Accident Date :15/8/2024

Location

: NEAR BEF SINGAPORE AVIATION

3P:

SNG6516L (INCOME)

C/Non	Ohi	Description	Liet C	S/Nett\$	Nett \$
S/Nos.	Qty	<u>Description</u>	<u>List\$</u>		Nett 2
1	1 pc	Front bumper	3186.60	du	
2	1 pc	Front bumper Lh ganrish (LOU)	610.20	*	
3	1 pc	Front &H head lamp	2818.70	art-	
4	1 pc	Front H signal lamp	810.20	cne/	
5	1 pc	Front &H step garnish	821.70	7	
6	1 pc	Front RH step garnish reflector	120.00	×	
7	1 pc	Front RH step aluminium (lower)	300.00	* 14	
8	1 pc	Front ILH step aluminium (upper)	300.00	×	
		From Sumper Ly garrigh strip 3110 ?			
		Front Ly Step garnish upoir Ry Sub Total:	8,967.40	0.00	0.00
	<u> </u>		25%	0%	0%
		After Less %:	6,725.55	0.00	0.00
		Labour			
1		To remove and replace damage parts	1200.00 600		
2		To spray painting.	800.00 600		
3		To check wiring.	200.00 50.		
		Sub Total:		2,200.00	
		Total:		8,925.55	
	1	After Less 20%:		7,140.44	

Chan San Choon

Director

DipEng, AAE MIMI, MSAE(Aust)

Tanphri 97495949 /62563561 wp: 22/8/242 245ph. 2/5 Resny after repair 5-4days tanfilm Climanto. won





24 hr accident call

AC8778 1999 MODILI



LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed

oplementary item(s) must be resurveyed and ...bject to final approval from Insurance Company

ladged to Repail or

5

XE91B1K ESTIMATEPg1