



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBD 2017U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	DENTED	\$1,520.00	\$1,520.00
1	REAR TAILGATE DYNA STICKER	NECESSARY	\$59.20	\$59.20
1	REAR TAILGATE TOYOTA STICKER	NECESSARY	\$130.00	\$130.00
4	REAR TAILGATE HINGES	NOT NECESSARY	\$277.20	\$0.00
1	REAR TAILGATE LOWER PANEL	TO REPAIR SEE LABOUR	\$698.10	\$0.00
2	REAR TAILGATE FLIP LOCK HANDLE LH & RH	NOT NECESSARY	\$318.80	\$0.00
2	REAR TAILLAMP LH & RH	N/S CUT	\$628.60	\$265.00
2	REAR TAILLAMP BRACKET LH & RH	NOT NECESSARY	\$143.80	\$0.00
2	REAR RUBBER STOPPED LH & RH	NOT NECESSARY	\$93.00	\$0.00
2	REAR RUBBER STOPPED BRACKET LH & RH	NOT NECESSARY	\$197.20	\$0.00
	LESS 25.00% DISCOUNT		(\$1,016.48)	(\$493.55)
			\$3,049.42	\$1,480.65
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE INN ALUMINIUM (SN)	NOT NECESSARY	\$300.00	\$0.00
1	REAR TAILGATE 70KM/H STICKER (SN)	NECESSARY	\$25.00	\$15.00
1	REAR TAILGATE 6 PAX STICKER (SN)	NECESSARY	\$25.00	\$15.00
1	REAR NO. PLATE (SN)	BENT	\$35.00	\$35.00
1	REAR NO. PLATE HOLDER (SN)	BENT	\$50.00	\$30.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	\$250.00	\$200.00
1	SET REAR REVERSE SENSOR BRACKET (SN)	BENT	\$80.00	\$40.00
1	REAR TAILGATE REFLECTIVE STICKER (SN)	NECESSARY	\$100.00	\$50.00
			\$865.00	\$385.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR TAILGATE LOWER PANEL		\$1,000.00	\$300.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREA		\$800.00	\$300.00
	TO CHECK WIRING, LAYOUT & REWIRE PARKING SENSOR		\$100.00	\$50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST PROOF AFFECTED AREA		\$100.00	\$30.00
			\$2,000.00	\$680.00
GRAND TOTAL			\$5,914.42	\$2,545.65
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$2,000.00
Report Ref No: CS/INC24080279/Aqh3				

TOTAL FOR SPARE PARTS: \$ 3,914.42 \$ 1,845.65
TOTAL FOR LABOUR : \$ 2,000.00 \$ 700.00
TOTAL REPAIR COST: \$ 5,914.42 \$ 2,545.65

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.