

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080281/UMA3Q2  
Date: 19/09/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_04  
Claimant Vehicle No : SLU6623K Insured Vehicle No : GBJ810C  
Date of Loss: 13/08/2024 Nature of Claim: TP Claim No: MFL2024D0009309

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU6623K  
Make & Model: BMW 116D, 1.5 D 5DR LED EU6 (A) Engine No: 35935106B37D15A  
Reg. Date: 11/12/2017 (Man. Year: 2017) Chassis No: WBA1V720505G87264  
Colour: Silver Odometer: 68955 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,161.00	1,956.15	2,204.85	52.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	550.00	1,050.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,761.00	2,506.15	3,254.85	56.50
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	5,761.00	2,000.00	3,761.00	65.28
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/08/2024  
Date Inspected: 20/08/2024 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)  
29 Ubi Road 4, Dickson Auto Centre  
Singapore 408619  
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2024)
Parts:	144	BMW 116D 1.5 D 5DR LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6623K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR COVER	Dented / Deformed	820.00 F	*820.00 FL
2	1		*BUMPER BRACKET REAR LH	Not Necessary	150.00 F	*- FL
3	1		*BUMPER BRACKET REAR RH	Not Necessary	150.00 F	*- FL
4	10		*BUMPER CLIPS	Necessary	20.00 F	*20.00 FL
5	1		*TOW EYE COVER REAR RH	Cut	52.00 F	*52.00 FL
6	1		*REVERSE CAMERA	Malfunction	795.00 F	*795.00 FL
7	1		*NUMBER PLATE	Dented	45.00 FS	*20.00 FS
8	1		*NUMBER PLATE HOLDER	Cut	40.00 FS	*20.00 FS
9	1		*REAR PANEL	Repair	500.00 F	*- FL
10	1		*BUMPER REAR REINFORCEMENT	Bent	330.00 F	*330.00 FL
11	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
12	2		*NUMBER PLATE LAMP REAR	Not Necessary	40.00 F	*- FL
13	1		*SENSOR BRACKET REAR (4 PCS /SET)	Serviceable	39.00 F	*- FL
14	4		*SENSOR BUMPER REAR	Not Necessary	200.00 F	*- FL
15	1		*TAILGATE LOCK	Not Necessary	250.00 F	*- FL
16	1		*REAR LAMP LH (OUTER)	Not Necessary	340.00 F	*- FL
17	1		*REAR LAMP RH (OUTER)	Not Necessary	340.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,161.00	2,057.00
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	100.85
Total Parts (S\$)	4,161.00	1,956.15

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE REAR BUMPER ,REAR LAMP LH (OUTER),REAR LAMP RH (OUTER) & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	New	400.00	200.00
2	TO SPRAY REAR BUMPER ,BUMPER REINFORCEMENT REAR & REAR PANEL	New	500.00	300.00
3	TO REPLACE /TRANSFER THE REAR BUMPER SENSORS ,REVERSE CAMERA & OTHER PARTS	New	200.00	30.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	20.00
5	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	200.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,600.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >