

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CT124080282/JNH3E2**Date:** 23/08/2024**REFERENCE**

Insured/Claimant:	YEO CHENG TEE	Policy No:	DMHCSNW00003862400
Date of Loss:	16/08/2024	Nature of Claim:	OD
		Claim No:	SNM24D204642/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA3862L		
Make & Model:	HYUNDAI DM SANTA FE, 2.1 D 2.2 CRDI AT 4WD SR (A)	Engine No:	D4HBFU314177
Reg. Date:	29/02/2016 (Man. Year: 2015)	Chassis No:	KMHCU81XSGU584178
Colour:	White	Odometer:	0 km
Engine Capacity:	2199 cc		
Market Value/New Car Price:	S\$41,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:		Rear Tyre Size:	255/40 R20
Front Left Side:	0 mm	Rear Left Side:	0 mm
Front Right Side:	0 mm	Rear Right Side:	Pirelli 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	0.00	1,250.00	-1,250.00	
Nett Amount (\$\$)	0.00	-1,250.00	1,250.00	

INSPECTION

Date of Assignment:	19/08/2024	Present Location:	DING AUTO PTE LTD (CARROS CENTRE)
Date Inspected:	19/08/2024	Inspected At:	DING AUTO PTE LTD (CARROS CENTRE) 60 JALAN LAM HUAT, #06-46/47 CARROS CENTRE Singapore 737869
Estimated Period of Repair:	0.0 days		

Adjuster: Elton**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$41,000.00
OMV :	\$33,026.00
PARF Rebate (1) :	\$21,030.00
Quota Premium Paid :	\$51,000.00
COE Rebate (2) :	\$7,632.00
Total Rebate (1) + (2) = :	\$28,662.00

The total amount incurred will be Market Value \$41,000.00 minus Total Rebate \$28,662.00 = \$12,338.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2024)
Parts:	M1-SUV	HYUNDAI DM SANTA FE 2.1 D 2.2 CRDI AT 4WD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA3862L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >