



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 6472R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT GRILLE	NOT NECESSARY	\$507.40	\$0.00
1	FRONT GRILLE CLIPS	NOT NECESSARY	\$39.00	\$0.00
1	FRONT RH HEADLAMP	NOT NECESSARY	\$569.10	\$0.00
1	FRONT RH HEADLAMP CLIPS	NOT NECESSARY	\$6.50	\$0.00
1	FRONT RH HEADLAMP LOWER BRACKET	NOT NECESSARY	\$31.40	\$0.00
1	FRONT BUMPER	TO REPAIR SEE LABOUR	\$624.00	\$0.00
2	FRONT BUMPER SIDE RETAINER L/R	BENT	\$46.00	\$46.00
1	FRONT BUMPER FOGLAMP GARNISH	NOT NECESSARY	\$75.00	\$0.00
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	\$207.20	\$0.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$421.60	\$0.00
1	FRONT RH FENDER	BENT	\$487.10	\$487.10
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	\$87.90	\$0.00
1	FRONT RH R15 SPORT RIM	BENT	\$420.00	\$420.00
1	FRONT RH SHOCK ABSORBER	NOT NECESSARY	\$469.30	\$0.00
1	FRONT RH KNUCKLE ARM	NOT NECESSARY	\$437.80	\$0.00
1	FRONT RH KNUCKLE BEARING	NOT NECESSARY	\$154.20	\$0.00
1	FRONT RH LOWER ARM	NOT NECESSARY	\$322.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$490.55)	(\$95.31)
			<b>\$4,414.95</b>	<b>\$857.79</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
			<b>\$60.00</b>	<b>\$0.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR		\$120.00	\$30.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, BEARING	NOT NECESSARY	\$350.00	\$0.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM		\$160.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,200.00	\$400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER REINFORCEMENT		\$1,300.00	\$300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$100.00	\$20.00
			\$3,230.00	\$830.00
<b>GRAND TOTAL</b>			<b>\$7,704.95</b>	<b>\$1,687.79</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$1,350.00</b>
Report Ref No: CS1/LIP24080290/Ence2				

MARKET VALUE: \$60,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,373.00=NETT VALUE: \$45,627.00

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.