50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Tel: +65 97687958 Fax: +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com

Reg. No. T07LL1273E (registered with limited liability)

## **AUTOMOBILE ASSESSMENT REPORT**

TO: ANG CHUNG SIONG DEREK

C/O: TSA TRANSPORT BLK 110B BIDADARI PARK DRIVE #06-242 SINGAPORE 342110 Our Reference: 0623/TT685
Date: 30-Jun-2023

ASSESSMENT OF VEHICLE NO. SMG 6472 R DATE OF LOSS: 29-May-2023

We have carried out a physical assessment at JEC AUTO SERVICE,

1 Kaki Bukit Ave 6 #02-11 Autobay @ Kaki Bukit Singapore 417883, according to your instruction

of 05-Jun-2023 and are pleased to submit our report herewith.

#### 1. VEHICLE PARTICULARS

Registration No.: SMG 6472 R

Make & Model: NISSAN NOTE 1.2 CVT

Year of Registration: 2018 Engine Capacity: 1198

Chassis No.: JN1TAAE12Z0982663

Engine No.: HR12262659J

Colour: GREY Mileage (km): 88902

#### 2. VEHICLE CONDITION

Bouy Paint: GOOD

Steering: SERVICEABLE Foot Brake: SERVICEABLE Parking Brake: SERVICEABLE

Modification: NIL

# 3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread: DUNLOP 185/60 R15 – 70% LH Make/Size/Thread: DUNLOP 185/60 R15 – 70%

Rear

RH Make/Size/Thread: DUNLOP 185/60 R15 - 70% LH Make/Size/Thread: DUNLOP 185/60 R15 - 70%

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Tel: +65 97687958 Fax: +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com

Reg. No. T07LL1273E (registered with limited liability)


# 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

#### 5. REMARKS

Market Value: Na Salvage Value: Na Repair Limit: Na

Estimated Amount: \$7,704.95
Adjusted Amount: \$6,104.87
Lu Sum: \$4,600.00
Estimated Repair Days: 5 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Tel: +65 97687958 Fax: +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com

Reg. No. T07LL1273E (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. SMG 6472 R

# PARTS (LIST ITEMS)

Description Con		Workshop's		Our
	Condition	Estim	ate	Assessment
FRONT GRILLE	Repair	x nn	507 40	_
FRONT GRILLE CLIPS	•			39.00
FRONT RH HEADLAMP	•			569.10
FRONT RH HEADLAMP CLIPS				6.50
FRONT RH HEADLAMP LOWER BRACKET	•			
FRONT BUMPER				31.40
FRONT BUMPER SIDE RETAINER L/R	• •	ΧK		624.00
FRONT BUMPER FOGLAMP GARNISH		v nn		46.00 /
FRONT BUMPER INNER SPONGE	·			**
	•			-
FRONT RH FENDER	•			
FRONT RH FENDER INNER SHIELD				487.10 /
				87.90
				420.00 /
		x nn	469.30	469.30
	Bent	x nn	437.80	437.80
	Jammed	x nn	154.20	154.20
THOM I AN LOWER ARIVI	Bent	x nn	322.00	322.00
	FRONT GRILLE FRONT GRILLE CLIPS FRONT RH HEADLAMP FRONT RH HEADLAMP CLIPS FRONT RH HEADLAMP LOWER BRACKET FRONT BUMPER FRONT BUMPER SIDE RETAINER L/R FRONT BUMPER FOGLAMP GARNISH FRONT BUMPER INNER SPONGE FRONT BUMPER REINFORCEMENT	FRONT GRILLE FRONT GRILLE CLIPS FRONT RH HEADLAMP FRONT RH HEADLAMP FRONT RH HEADLAMP CUIPS FRONT RH HEADLAMP LOWER BRACKET FRONT BUMPER FRONT BUMPER FRONT BUMPER SIDE RETAINER L/R FRONT BUMPER FOGLAMP GARNISH FRONT BUMPER INNER SPONGE FRONT BUMPER REINFORCEMENT FRONT BUMPER REINFORCEMENT FRONT RH FENDER FRONT RH FENDER FRONT RH FENDER INNER SHIELD FRONT RH FENDER INNER SHIELD FRONT RH SPORT RIM Bent FRONT RH SHOCK ABSORBER FRONT RH KNUCKLE ARM FRONT RH KNUCKLE BEARING FRONT RH KNUCKLE BEARING FRONT RH LOWER ARM	FRONT GRILLE FRONT GRILLE CLIPS FRONT GRILLE CLIPS FRONT RH HEADLAMP FRONT RH HEADLAMP FRONT RH HEADLAMP CLIPS FRONT RH HEADLAMP LOWER BRACKET FRONT BUMPER FRONT BUMPER FRONT BUMPER SIDE RETAINER L/R FRONT BUMPER FOGLAMP GARNISH FRONT BUMPER FORLAMP GARNISH FRONT BUMPER INNER SPONGE FRONT BUMPER REINFORCEMENT FRONT BUMPER REINFORCEMENT FRONT RH FENDER FRONT RH SHOCK ABSORBER FRONT RH KNUCKLE BEARING FRONT RH KNUCKLE BEARING FRONT RH LOWER ARM FRONT RH LOWER ARM	FRONT GRILLE FRONT GRILLE FRONT GRILLE CLIPS FRONT GRILLE CLIPS FRONT RH HEADLAMP FRONT RH HEADLAMP FRONT RH HEADLAMP CLIPS FRONT RH HEADLAMP LOWER BRACKET FRONT RH HEADLAMP LOWER BRACKET FRONT BUMPER FRONT BUMPER FRONT BUMPER FRONT BUMPER SIDE RETAINER L/R FRONT BUMPER FOGLAMP GARNISH FRONT BUMPER FOGLAMP GARNISH FRONT BUMPER INNER SPONGE FRONT BUMPER REINFORCEMENT FRONT BUMPER REINFORCEMENT FRONT RH FENDER SHIELD FRONT RH FENDER INNER SHIELD FRONT RH SHOCK ABSORBER FRONT RH KNUCKLE BEARING FRONT RH KNUCKLE BEARING FRONT RH KNUCKLE BEARING FRONT RH LOWER ARM

Less 10% discount Parts Total:

4,905.50	3,694.30
490.55	369.43
4,414,95	3,324.87

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Tel: +65 97687958 Fax: +65 68264112 Email amas@aeonac.com.sg/amasopm@gmail.com

Reg. No. T07LL1273E (registered with limited liability)

## ASSESSMENT REPORT FOR VEHICLE NO. SMG 6472 R

## **SPECIAL NETT ITEMS**

1 FRONT BUMPER CLIPS - SET1 FRONT RH FENDER INNER SHIELD CLIPS - SET

Necessary Necessary 30.00 x nn 30.00 30.00 x nn 30.00

Special Nett Total:

TOTAL (PARTS & LABOUR) \$

60.00 60.00

#### **LABOUR**

S/N	Description	Workshop's Estimate	Our Assessment
	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	120.00	30 100.00
2	To remove, change front suspension parts, absorber, lower arm, knuckle arm, bearing.	350.00	X 300.00
3	To road test driving, check and resetting wheel alignments system.	160.00	80 140.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	400 1,000.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and realign body structure, body alignments and damaged consistent to the accident.	1,300.00	3001,100.00
6	To apply anti-rust chemical on repaired and replaced panel.	100.00	20 80.00
	Labour Total :	3,230.00	2,720.00

The vorkshop has agreed to undertake the repair on a Lump Sum basis.

inal adjusted Lump Sum contract amount is

\$4,600.00 (SINGAPOI

(SINGAPORE DOLLARS FOUR THOUSAND SIX HUNDRED ONLY)

4 days


6,104.87

7,704.95

Amas Ong Automobile Assessor


















Aeon Auto Consultants LLP







