



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080306/Uqp3
16 RAFFLES QUAY	Date:	04/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7037G	Veh. Inspected	SMQ 7627C
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24007270MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	19/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA VIOS (A)	C.C	1496
Engine No.	2NR5401664	Year of Reg.	29/11/2019
Chassis No.	MR2B23F3801192230	Colour	GREY
Odometer	112320 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	MICHELIN	6
L/H Front Tyre	185/60R15	MICHELIN	6
R/H Rear Tyre	185/60R15	MICHELIN	6
L/H Rear Tyre	185/60R15	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	16/08/2024	Inspection Date	20/08/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days