



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501329

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:EMILY TAN

INV Date 07/03/2025
Reference CD/FCI24080323/Rua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJR 6088U
Insured Veh. SH 9023H
Claim No. D24007211MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 14/08/2024
Inspection Date 02/09/2024

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CD/FCI24080323/Rua3q2	
		Date:	07/03/2025	
		Code:	FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SH 9023H	Veh. Inspected	SJR 6088U	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24007211MFCT/CTPL/TPD 2	Excess	\$0.00	
Assign From	CHRIS LIM	Assign Date	20/08/2024	
2. Vehicle Details				
Make & Model	HONDA CRV 1.5 TURBO CVT 5SEATER	C.C	1498	
Engine No.	L15C21172724	Year of Reg.	11/07/2024	
Chassis No.	MRHRS3837RP070017	Colour	WHITE	
Odometer	2387 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	235/65 R17	GOODYEAR	6	
L/H Front Tyre	235/65 R17	GOODYEAR	6	
R/H Rear Tyre	235/65 R17	GOODYEAR	6	
L/H Rear Tyre	235/65 R17	GOODYEAR	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2024	Inspection Date	02/09/2024	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJR 6088U

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$100.00	\$30.00
1	FACE FR BUMPER (SN)	TO REPAIR SEE LABOUR	\$411.22	\$0.00
1	FACE FR BUMPER LOWER (SN)	SCRATCHED	\$71.17	\$71.17
1	SPACER,R.FR.BUMPER SIDE (SN)	NECESSARY	\$3.07	\$3.07
1	SPACER,L.FR.BUMPER SIDE (SN)	NECESSARY	\$3.07	\$3.07
1	PROTECTOR SET,L WHEEL ARCH (SN)	CRACKED	\$32.85	\$32.85
1	HEADLIGHT ASSY,L (SN)	SERVICEABLE	\$865.35	\$0.00
1	LIGHT ASSY ,L.FR SIDE REFLECTOR (ADDITIONAL) (SN)	MISSING	\$53.10	\$53.10
			\$1,539.83	\$193.26
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	INSPECT FR LIGHTING MECHANISMS & FOCUS		\$280.00	\$250.00
	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON.INCLUSIVE OF THE REPAIR OF FACE FR BUMPER.		\$1,950.00	\$975.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS		\$2,040.00	\$520.00
			\$4,270.00	\$1,745.00
GRAND TOTAL			\$5,809.83	\$1,938.26
RECOMMENDED COST OF REPAIRS				\$1,938.26
Report Ref No: CD/FCI24080323/Rua3q2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U



PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U



PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U



PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U



PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U



PHOTOGRAPHS FOR VEHICLE NO. : SJR 6088U

