

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/III24080324/AUA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747\_03  
**Claimant Vehicle No :** SLA1688L **Insured Vehicle No :** SNH7036T  
 Date of Loss: 19/08/2024 Nature of Claim: TP Claim No: MFL2024D0009685

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLA1688L**  
 Make & Model: TOYOTA CAMRY, 2.4 ABS AIRBAG (A) Engine No: 2AZE049228  
 Reg. Date: 16/07/2007 (Man. Year: 2007) Chassis No: MR053BK4007014210  
 Colour: Silver Odometer: 169238 km  
 Engine Capacity: 2362 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,703.05	18,988.97	9,714.08	33.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,960.00	5,040.00	3,920.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,663.05</b>	<b>24,028.97</b>	<b>13,634.08</b>	<b>36.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>18,000.00</b>		
<b>(S\$)</b>	37,663.05	18,000.00	19,663.05	52.21
<b>+ GST 9.00/9.00% (S\$)</b>	3,389.67	1,620.00	1,769.67	52.21
<b>Nett Amount (S\$)</b>	<b>41,052.72</b>	<b>19,620.00</b>	<b>21,432.72</b>	<b>52.21</b>
<b>+ Loss of Use (22.0 x S\$100.00/day) (S\$)</b>		2,200.00		
<b>+ Doc/Search Fee (S\$)</b>		27.25		
<b>Nett Liability (S\$)</b>		<b>21,847.25</b>		

**INSPECTION**

Date of Assignment: 21/08/2024  
 Date Inspected: 21/08/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)  
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit  
 Singapore 415875  
 Estimated Period of Repair: 18.0 days

**Adjuster:** ADRIAN LING**Manager:** NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2024)
<b>Parts:</b> 143	TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLA1688L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	520.00 FL	*520.00 FL
2	2		*FRONT BUMPER BOTTOM COVER GARNISH	Not Necessary	550.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP	Not Necessary	430.00 FL	*- FL
4	2		*FRONT BUMPER FOGLAMP COVER	Cracked	190.00 FL	*190.00 FL
5	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	30.00 FL	*- FL
6	1		*FRONT BUMPER GRILLE (UPPER)	Cracked	570.00 FL	*570.00 FL
7	1		*FRONT BUMPER GRILLE (LOWER)	Cracked	158.00 FL	*158.00 FL
8	1		*FRONT BUMPER GRILLE LOGO	Necessary	65.00 FL	*65.00 FL
9	2		*FRONT BUMPER RETAINER	Not Necessary	170.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	465.00 FL	*465.00 FL
11	1		*FRONT BUMPER SPONGE	Cracked	140.00 FL	*140.00 FL
12	2		*HEADLAMP	Cracked	5,192.00 FL	*5,192.00 FL
13	2		*FRONT FENDER INNER COWLING	Not Necessary	350.00 FL	*- FL
14	1		*BONNET	Dented	1,425.00 FL	*1,425.00 FL
15	2		*BONNET DAMPER	Not Necessary	260.00 FL	*- FL
16	1		*BONNET INSULATOR	Not Necessary	505.00 FL	*- FL
17	2		*BONNET HINGE	Not Necessary	140.00 FL	*- FL
18	1		*BONNET RUBBER	Not Necessary	75.00 FL	*- FL
19	1		*BONNET LOCK	Not Necessary	150.00 FL	*- FL
20	2		*BONNET STOPPER	Not Necessary	40.00 FL	*- FL
21	1		*BRACE PANEL	Bent	125.00 FL	*125.00 FL
22	1		*RADIATOR SUPPORT PANEL	Buckled	1,035.00 FL	*1,035.00 FL
23	1		*AIR DUCT	Not Necessary	185.00 FL	*- FL
24	2		*HORN	Not Necessary	240.00 FL	*- FL
25	1		*AIRCON CONDENSOR	Dented	1,620.00 FL	*1,620.00 FL
26	1		*AIRCON PIPE	Not Necessary	387.00 FL	*- FL
27	1		*RADIATOR	Not Necessary	2,125.00 FL	*- FL
28	2		*RADIATOR SIDE GARNISH	Not Necessary	320.00 FL	*- FL
29	1		*BOOTLID	Buckled	910.00 FL	*910.00 FL
30	1		*BOOTLID DETECTOR	Obstructed	395.00 FL	*- FL
31	2		*BOOTLID LAMP	Cut	840.00 FL	*840.00 FL
32	1		*BOOT LID EMBLEM CAMRY	Necessary	65.00 FL	*65.00 FL
33	1		*BOOT LID EMBLEM 2.4	Necessary	60.00 FL	*60.00 FL
34	1		*BOOTLID LOGO	Necessary	80.00 FL	*80.00 FL
35	2		*BOOTLID HINGE	Not Necessary	252.00 FL	*- FL
36	2		*BOOTLID STOPPER	Not Necessary	38.00 FL	*- FL
37	1		*BOOTLID INSULATOR	Not Necessary	265.00 FL	*- FL
38	1		*BOOTLID LOCK	Not Necessary	395.00 FL	*- FL
39	1		*BOOTLID CATHER	Not Necessary	25.00 FL	*- FL
40	1		*BOOTLID WEATHERSTRIP	Cut	240.00 FL	*240.00 FL
41	1		*REAR NUMBER PLATE GARNISH WITH MOULDING	Not Necessary	380.00 FL	*- FL
42	1		*REAR BUMPER	Distorted	560.00 FL	*560.00 FL
43	1		*REAR BUMPER REFLECTOR	N/S Cut	150.00 FL	*75.00 FL
44	1		*REAR BUMPER SIDE RETAINER (SIDE)	N/S Damaged	140.00 FL	*70.00 FL
45	1		*REAR BUMPER RETAINER (CORNER)	N/S Damaged	160.00 FL	*80.00 FL
46	2		*REAR BUMPER SCREW COVER GARNISH	Not Necessary	56.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER REINFORCEMENT	Dented	405.00 FL	*405.00 FL
48	1		*REAR DOOR LH	Dented	1,390.00 FL	*1,390.00 FL
49	1		*REAR DOOR INNER LOCK LH	Jammed	395.00 FL	*395.00 FL
50	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	210.00 FL	*- FL
51	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	650.00 FL	*- FL
52	2		*TAILLAMP	N/SCracked / O/S Cut	1,070.00 FL	*1,070.00 FL
53	1		*TAILLAMP PANEL LH	Distorted	230.00 FL	*230.00 FL
54	1		*REAR FENDER LH	Distorted	995.90 FL	*995.90 FL
55	1		*REAR FENDER INNER PANEL LH	Repair	859.10 FL	*- FL
56	1		*REAR FENDER INNER COWLING	Not Necessary	810.00 FL	*- FL
57	2		*REAR FENDER INNER TRIM	Crumpled	1,350.00 FL	*675.00 FL
58	1		*REAR WINDSCREEN MOULDING	Necessary	240.00 FL	*240.00 FL
59	1		*REAR END PANEL	Distorted	620.00 FL	*620.00 FL
60	1		*REAR END PANEL TOP GARNISH	Deformed	420.00 FL	*420.00 FL
61	1		*REAR FLOOR PANEL TOP BOARD	Torn	280.00 FL	*280.00 FL
62	1		*REAR FLOOR PANEL	Distorted	1,140.00 FL	*1,140.00 FL
63	1		*REAR FLOOR INNER SUPPORT PANEL	Distorted	385.20 FL	*385.20 FL
64	1		*REAR FLOOR SIDE PANEL LH	Distorted	586.20 FL	*586.20 FL
65	1		*REAR SPARE TYRE BOLT	Bent	32.00 FL	*32.00 FL
66	1		*REAR CHASSIS EXTEND MEMBER LH	Distorted	796.00 FL	*796.00 FL
67	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
68	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
69	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
70	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
71	1		*RADIATOR SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
72	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
73	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
74	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
75	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
76	1		*BOOTLID SIDE LINING (SPECAIL TYPE)	Necessary	200.00 FS	*60.00 FS
77	1		*REAR DOOR SEALANT	Not Necessary	120.00 FS	*- FS
78	1		*REAR DOOR INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
79	1		*REAR DOOR SIDE LINING (SPECAIL TYPE)	Necessary	100.00 FS	*60.00 FS
80	1		*SET TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
81	1		*REAR FENDER SEALANT RH	Necessary	150.00 FS	*60.00 FS
82	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
83	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
84	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
85	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
86	1		*REAR END PANLE INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
87	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	350.00 FS	*200.00 FS
88	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>37,537.40</b>	<b>25,025.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	8,834.35	6,036.33
<b>Total Parts (\$)</b>	<b>28,703.05</b>	<b>18,988.97</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,600.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	600.00
3	REFOCUS HEADLAMP BEAM	New	60.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	PANEL BEATING REMOVAL AND REPLACING PARTS	New	2,400.00	1,800.00
7	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,200.00
8	TUFF COAT	New	250.00	120.00
9	WIRING CHECK	New	160.00	30.00
10	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	150.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
14	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
15	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
16	REMOVE AND REFIX REAR EXHAUST	New	180.00	0.00
17	TRANSFER REAR DOOR MECHANISM	New	80.00	40.00
18	REMOVE & REINSTALL REAR WINDOW GLASS	New	80.00	40.00
19	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	80.00	60.00
20	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>8,960.00</b>
				<b>5,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >