



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNF 6017R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LH ROOF TOP SIDE PANEL	DENTED	\$1,713.53	\$1,025.00
1	FRONT DOOR	NOT NECESSARY	\$1,358.76	\$0.00
1	FRONT DOOR GLASS	CUT	\$585.39	\$585.39
1	FRONT DOOR INNER WEATHER	TORN	\$143.39	\$143.39
1	FRONT DOOR GLASS CHANNEL	DENTED	\$128.05	\$128.05
1	FRONT DOOR SIDE MIRROR	DAMAGED	\$1,041.95	\$898.00
1	FRONT DOOR SIDE MIRROR HOUSING	NOT NECESSARY	\$173.68	\$0.00
1	FRONT DOOR FRAME BLACK STICKER	NECESSARY	\$43.42	\$43.42
1	FRONT DOOR FRAME SIDE GARNISH	CUT	\$59.28	\$59.28
1	REAR LH DOOR	DENTED	\$1,459.38	\$1,295.00
1	REAR LH DOOR GLASS	SHATTERED	\$731.64	\$731.64
1	REAR LH DOOR GLASS OUTER MOULDING	NOT NECESSARY	\$119.99	\$0.00
1	REAR LH DOOR GLASS REAR SIDE GARNISH	CRACKED	\$159.38	\$159.38
1	REAR LH DOOR GLASS INNER RUBBER	CUT	\$224.25	\$224.25
1	REAR LH DOOR GLASS CHANNEL	NOT NECESSARY	\$142.22	\$0.00
1	REAR LH FENDER GLASS	SHATTERED	\$731.64	\$731.64
1	REAR LH FENDER SIDE GARNISH	DEFORMED	\$265.98	\$265.98
1	REAR LH SAFETY BELT GARNISH	NOT NECESSARY	\$354.64	\$0.00
1	ROOF TOP UPHOLSTERY	NOT NECESSARY	\$1,615.77	\$0.00
	<b>LESS 20.00% DISCOUNT</b>		(\$2,210.47)	(\$1,258.08)
			<b>\$8,841.87</b>	<b>\$5,032.34</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LH REAR FENDER GLASS SEALANT + FRONT WINDSCREEN SEALANT (SN)	NECESSARY	\$200.00	\$100.00
			<b>\$200.00</b>	<b>\$100.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE + REFIX DOOR GLASS AND FITTINGS		\$300.00	\$60.00
	REMOVE + REFIX UPHOLSTERY		\$300.00	\$60.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE + REINSTALL REAR LH SAFETY BELT	NOT NECESSARY	\$100.00	\$0.00
	REMOVE + REFIX WINDSCREEN + FENDER GLASS		\$300.00	\$180.00
	REMOVE, REPLACE + REPAIR CONSISTENT TO THE ACCIDENT		\$1,800.00	\$800.00
	RESPRAY PAINTING		\$1,600.00	\$600.00
	TUFF KOTE		\$100.00	\$60.00
	TOWING FEE	NOT NECESSARY	\$150.00	\$0.00
			\$4,650.00	\$1,760.00
GRAND TOTAL			\$13,691.87	\$6,892.34
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,500.00
Report Ref No: CS/SMO24080330/Aqp3				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.