



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YQ 3260K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN GLASS	BROKEN	\$991.52	\$991.52
1	FRONT WINDSCREEN WEATHERSTRIP	CUT	\$593.26	\$593.26
1	WIPER PANEL	NOT NECESSARY	\$456.97	\$0.00
2	WIPER BLADE	CUT	\$124.00	\$62.00
2	WIPER ARM	BENT	\$278.56	\$139.28
1	WIPER LINK	NOT NECESSARY	\$752.27	\$0.00
1	WIPER MOTOR	NOT NECESSARY	\$787.70	\$0.00
1	SIDE MIRROR ASSY, LH	CUT	\$112.28	\$112.28
1	ROUND MIRROR, LH	CRACKED	\$65.26	\$65.26
1	MIRROR STAY ASSY, LH	NOT NECESSARY	\$546.14	\$0.00
1	MIRROR STAY COVER, LH	CUT	\$16.53	\$16.53
1	FRONT CORNER PANEL, RH	NOT NECESSARY	\$603.04	\$0.00
1	SIDE MIRROR ASSY, RH	NOT NECESSARY	\$112.28	\$0.00
1	MIRROR STAY COVER, RH	NOT NECESSARY	\$16.53	\$0.00
1	DASHBOARD (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	<b>LESS 0.00 / 25.00% DISCOUNT</b>		\$0.00	(\$495.03)
			\$5,456.34	\$1,485.10

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	IU BRACKET (SN)	NECESSARY	\$45.00	\$45.00
1	IU STICKER (SN)	NECESSARY	\$45.00	\$45.00
			\$90.00	\$90.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REPLACE FRONT WINDSCREEN		\$180.00	\$120.00
	TO REMOVE AND INSTALL DASHBOARD		\$280.00	\$150.00
	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT FRONT PORTION. INCLUSIVE OF THE REPAIR OF DASHBOARD		\$900.00	\$200.00
	TO CHECK AND RECTIFY WIRING CONNECT AND DISCONNECT	NOT NECESSARY	\$150.00	\$0.00
	TO PUTTY, RESPRAY AND POLISH ON ACCIDENT FRONT PORTION		\$750.00	\$200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING ON AFFECTED AREA	NOT NECESSARY	\$120.00	\$0.00
			\$2,380.00	\$670.00
GRAND TOTAL			\$7,926.34	\$2,245.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,600.00
Report Ref No: CS/LIP24060116/Rvh3e2				

MARKET VALUE: \$91,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,448.00=NETT VALUE: \$69,552.00

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS