

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24080334/RNP3E2**Date:** 07/10/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SMU8961J **Insured Vehicle No :** SND3789B

Date of Loss: 15/08/2024 Nature of Claim: TP Claim No: DMPC2401071H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU8961J**

Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B5672756

Reg. Date: 02/09/2020 (Man. Year: 2020) Chassis No: JHMRU1810JX202748

Colour: Blue Odometer: 62061 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	516.08	516.08	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	800.00	60.00	6.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,376.08</b>	<b>1,316.08</b>	<b>60.00</b>	<b>4.36</b>
<b>+ GST 9.00/9.00% (S\$)</b>	123.85	118.45	5.40	4.36
<b>Nett Amount (S\$)</b>	<b>1,499.93</b>	<b>1,434.53</b>	<b>65.40</b>	<b>4.36</b>

INSPECTION

Date of Assignment: 20/08/2024

Date Inspected: 21/08/2024 Inspected At: Puan Chew Motor Work Pte Ltd (Pandan)  
Blk K #01-12, Pandan Loop Industrial Estate  
Singapore 128219

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Oct 2024)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU8961J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Bent	444.10 FL	*444.10 FL
2	1		*FRONT N/S FENDER PROTECTOR	Scratched	201.00 FL	*201.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					645.10	645.10
- List Item Discount on L Items 20.00/20.00% (S\$)					129.02	129.02
Total Parts (S\$)					516.08	516.08

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE DAMAGED PARTS,KNOCK OUT,CUT AND WELD BODY PANEL PARTS WHERE NECESSARY,STRAIGHTEN AND RESHAPE,REPOSITION AND REALIGN REPLACEMENT PARTS TO THE ORIGINAL POSITION	New	380.00	350.00
2	SPRAY PAINTING OF ACCIDENT SECTIONS	New	480.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>860.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >