



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO XE 7686P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER (CONSISTENT)	DENTED	\$2,588.78	\$2,450.00
1	FRONT LAMP GRILLE (CONSISTENT)	TO REPAIR SEE LABOUR	\$875.68	\$0.00
1	FRONT BUMPER SENSOR - LH (CONSISTENT)	SERVICEABLE	\$788.68	\$0.00
1	STEP PANEL ALUMINIUM LOWER - LH (CONSISTENT)	BENT	\$937.55	\$937.55
1	STEP PANEL ALUMINIUM HOLDER LOWER - LH (CONSISTENT)	TO REPAIR SEE LABOUR	\$1,108.55	\$0.00
1	STAND PANEL - LH (CONSISTENT)	NOT NECESSARY	\$1,255.67	\$0.00
1	STAND PANEL REFLECTOR - LH (CONSISTENT)	NOT NECESSARY	\$375.68	\$0.00
	<b>LESS 0.00 / 10.00% DISCOUNT</b>		\$0.00	(\$338.76)
			<b>\$7,930.59</b>	<b>\$3,048.79</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO KNOCK & RENEW ALL ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT LAMP GRILLE AND STEP PANEL ALUMINIUM HOLDER LOWER - LH.		\$1,000.00	\$320.00
	TO RUST PROOFING ON AFFECTED AREA	NOT NECESSARY	\$680.00	\$0.00
	TO SPRAY & PAINTING ON AFFECTED AREA		\$850.00	\$400.00
			<b>\$2,530.00</b>	<b>\$720.00</b>

<b>GRAND TOTAL</b>	<b>\$10,460.59</b>	<b>\$3,768.79</b>
--------------------	--------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$3,000.00</b>
---	--	-------------------

Report Ref No: CS/HSB24060117/Uqp3

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser