



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS HSBC LIFE (SINGAPORE) PTE LTD	Ref:	CS/HSB24060117/Uqp3
10 MARINA BOULEVARD #48-01 MARINA BAY	Date:	18/06/2024
FINANCIAL CENTRE TOWER 2 SINGAPORE 018983	Code:	HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8385L	Veh. Inspected	XE 7686P
Policy No.	VFX/P2419140	Coverage	0
Claim No.	S3M04NF8	Excess	\$0.00
Assign From	OH VALE	Assign Date	18/06/2024

2. Vehicle Details

Make & Model	CAMC HN3251	C.C	11813
Engine No.	CM6D2840060122A60012	Year of Reg.	27/09/2022
Chassis No.	LZ5N2DD38NB001955	Colour	GREEN/BLUE
Odometer	75036 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80R22.5	AGATE	6
L/H Front Tyre	295/80R22.5	AGATE	6
R/H Rear Tyre	295/80R22.5	AEOLUS	6
L/H Rear Tyre	295/80R22.5	AEOLUS	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/06/2023	Inspection Date	21/06/2024
Survey held at	HUP LIAN HUAT ENGINEERING WORKS - 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE SINGAPORE 539278		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days